

Discover. Connect. Advance.

### MACOMB COMMUNITY COLLEGE CENTER CAMPUS

FACILITIES ASSESSMENT AND DEFERRED MAINTENANCE CAPITAL PLANNING REPORT

IDS Project No. 21195-4000

November 2023

INTRODUCTION	TAB 1
EXECUTIVE SUMMARY	TAB 2
REPORT SUMMARY	TAB 3
FCI INDEX	TAB 4
CAMPUS MAPS	TAB 5
BUILDING SUMMARIES	ТАВ 6

BUILDING CA

- BUILDING CB
- BUILDING CC
- BUILDING CD
- BUILDING CE
- BUILDING CFBUILDING CG
- BUILDING CH
- BUILDING CI
- BUILDING CK
- BUILDING CL
- BUILDING CM
- BUILDING CN
- BUILDING CP
- BUILDING CR
- BUILDING CS
- UNIVERSITY CENTER 1
- UNIVERSITY CENTER 2
- UNIVERSITY CENTER 3
- UNIVERSITY CENTER 4

# TAB 1

Integrated Design Solutions, LLC (IDS) was commissioned by Macomb Community College to conduct a Facility Condition Assessment (FCA) of all buildings located at Center Campus. This assessment will serve as a means to update the existing FCA and Deferred Maintenance Capital Plan. The survey was conducted between September 2022 and March 2023. Each building was thoroughly surveyed with the assistance of Macomb Community College personnel.

The following report compiles a list of all deficient building, mechanical, electrical and code related items that, in our professional opinion, will require replacement, enhancement and/or repair in order to meet the goals of preserving the assets of each building.

The IDS survey team consisted of senior level individuals with extensive knowledge in each of the building categories surveyed.

# TAB 2

This Facilities Assessment and deferred Maintenance Capital Planning Study, was updated using recent project data, contractor bids and Construction Manager estimates to accomplish the following objectives:

- Provide an inventory of the College's facilities in a database format to be easily updated and maintained.
- Determine the general condition of the facilities owned by Macomb Community College and provide the data in a concise format, allowing quick determination of the current replacement value and condition of each facility.
- Determine a Facilities Condition Index (FCI) for each assessed building and an aggregate FCI for all facilities at Macomb Community College. The FCI is a benchmark index that rates the condition of existing College buildings and is used by facilities managers nationwide to quantify and prioritize deferred maintenance projects for capital planning purposes.
- Assist Macomb Community College in meeting its Mission Statement, Strategic Goals and Institutional Vision through timely
  maintenance of the physical backbone of the College the buildings of Macomb Community College.

Estimated costs are itemized by architectural, mechanical, and electrical trades and are totaled under Construction Costs and include any material and labor costs without additional mark-ups. The Project Cost total includes a 45 percent mark-up on construction costs to include such items as A/E design fees, construction contingencies, reimbursable expenses and commissioning. All costs have been expressed in 2023 dollars. Therefore, any work implemented later than 2023 will require an adjustment. In some cases, due to the nature of the work, quantities were estimated and assumptions made in order to establish the course of action. Further development and investigation during future implementation phases will be necessary to determine a more accurate scope of work and a more precise budget estimate.

All deficiencies identified in this report total \$38,740,667. Category deficiencies breakdown in the following manner: architectural items \$4,382,595 (includes code related items), mechanical items \$11,623,145 and electrical items \$22,734928. All costs include a 45% mark-up to include "soft" costs associated with, and incremental to, actual construction costs.

Facility Condition Assessment team consisted of the following individuals:

### Administrative Team

Macomb Community College Executive Director of Facilities & Operations	William Simonson
Macomb Community College Director of Administrative Services	Bernard Jacobs
IDS Project Manager	Matthew Beck
IDS Principal-in-Charge	Michael Nowicki

### Facility Assessment Team

Architectural	
Mechanical	Frank Lesner
Electrical	Scott Batzold

# TAB 3

### **GLOSSARY OF TERMS**

### **Building Components**

The table below shows the building components used in the report. These are the basic components having a major influence on the replacement value of a building.

Category	Component Name
Envelope	Roof
	Glazing
	Cladding
Mechanical	HVAC Equipment
	Plumbing
	Fire Protection
Electrical	Power
	Lighting
Code/ADA	

### **Building Use Types**

The table below shows general building use types and their respective current construction costs per square foot used to develop this database. These costs, based on regionally weighted, preliminary construction cost data provided by contractors, historical cost databases and data from RS Means are for typical college and university buildings. Buildings may contain various uses, and each use is portioned to create the overall building replacement value per square foot.

Use Туре	Cost/SF
Administration	\$420
Auditorium	\$585
Student Services	\$410
Classroom	\$400
Lab	\$630
Library	\$370

### **Building Replacement Value (CRV)**

The CRV is the cost to construct a typical replacement building in today's dollars. The figure is based on the square footage of the current structure and the estimated current construction cost for that type of structure. Since some buildings are conglomerations of different uses (i.e.: classroom, library, administration) the CRV is based on estimated proportions of use types in each building. By the nature of the calculations and square foot construction costs, the current replacement value has a  $\pm 20\%$  margin of error and will change annually due to market demands.

### **Facilities Condition Index (FCI)**

The Association of Higher Education Facilities Officers (APPA) recommends that the FCI for any given building should not exceed 5% for the building to be considered in "Good" condition. The rating of "Fail" indicates that the building requires some attention to bring it up to standard, with some problem areas potentially requiring immediate attention. The rating of "Poor" indicates that the building needs urgent attention to prevent the existing problems from affecting other building systems and compounding future repair costs.

### **Deferred Maintenance Budget (DMB)**

This is the cost of upkeep of buildings and equipment postponed from the normal operating budget cycle.

### DMB Equilibrium (Annual Cost to Maintain Current DMB)

This is the dollar amount to be invested annually to keep the FCI (and DMB) from deteriorating - regardless of the current condition of the building.

The number is based on a national accepted rule of 2% of the CRV and assumes that building components have a 50-year renewal cycle and depreciate along a straight line. The assumptions were made to simplify calculations; in reality, building components do not expire according to straight-line depreciation, and most components will require replacement within 30-40 years (excluding structure and foundation).

To restate - this actual investment will only maintain the existing FCI and do little or nothing to reduce any existing backlog.

### Five Year Cumulative Deferred Maintenance Budget (5 Year DMB)

Similar to the One Year DMB, the Five Year DMB represents the total value of projects that will require attention within the next five years, including those that fall under the One Year DMB. This value is included to help determine the investment required over the next five years to repair and/or replace problem items before they become critical.

The Five Year DMB is often more telling of a buildings condition than the One Year DMB, since the first year number focuses primarily on life safety, code compliance and collateral damage. Most maintenance issues are not so critical as to fall into this category but often become so within 5 years.

### Five Year DMB Excess

Similar to the One Year DMB Excess value, this amount represents the investment to bring the DMB in line with the APPA benchmark of 5% of the Current Replacement Value. In situations where a building is in better than "Good" condition a bit more difficult over a five year span, the five year DMB excess is shown as zero.

This number is a good starting point for determining budgets - it allows the college to see what to spend to bring buildings into the APPA 'Good" range - with the understanding that complete elimination of the deferred Maintenance Budget is not a likely scenario.

### **Observation Highlights**

This is a focused list of field observations, highlighting major repair/replacement items and recently completed work.

### Vital Statistics

Basic building information - building use types, year built, building area in square feet and number of floors.

### **Code and Barrier Free Requirements**

Building and barrier free codes have changed extensively since many of the buildings on campus were constructed. Attempting to apply today's codes to these buildings is not always practical, but nonetheless, provides a benchmark to evaluate existing conditions. Mile there is no code mandated requirement to bring an existing building up to current code requirements, any new work would be required to meet current codes.

Renovation work will be governed by the Michigan Rehabilitation Code for Existing Buildings as well as current NFPA life safety requirements. Additionally, renovation work in excess of 50 percent of the building's area will likely require total building code compliance.

Contributing factors that make current code compliance problematic include limitations imposed by existing infrastructure that may prevent or make code compliance extremely difficult, both physically and monetarily. As a result, it may be necessary to consider equivalent code measures or combinations of code systems to achieve a desired life safety improvement or code compliance objective.

In addition to the Michigan Barrier Free Design Code, there are continuing obligations under the Americans with Disabilities Act (ADA) to remove barriers. The ADA is a civil rights act, not a code or standard and therefore, no agency verifies compliance. The Act expects compliance with the intent of the Act, which is to eliminate discrimination of the disabled. Portions of the buildings that are accessible to the public and students fall under the 'public accommodations" classification. These areas are governed by Title III of the ADA that requires the owner to make "readily achievable" changes that are in compliance with the ADA. The barrier free noncompliance issues in this report are based on full compliance to all requirements, although for reasons stated above, removal of all barriers may not be required at this time.

The following codes and standards represent the primary regulations in effect at the time of this report and that would apply to the college. At the time projects are actually implemented, the most current codes and standards that are in effect at the time must be utilized.

Building	2015 Michigan Rehabilitation code, Michigan Department of Licensing and Regulatory Affairs, Bureau of Construction Codes, 2015 Michigan Building Code, incorporating the 2015 Edition of the International Building Code.
	Michigan Department of Licensing and Regulatory Affairs, Bureau of Fire Services, Rules for Schools, Colleges and Universities, 2016, incorporating the 2015 Edition of the NFPA 101 Life Safety Code.
Barrier Free:	Michigan Department of Licensing and Regulatory Affairs, 2015 Michigan Building Code, incorporating the 2015 Edition of the International Building Code.
	Americans with Disabilities Act (ADA), 2010, Standards for Accessible Design
Elevator:	Michigan Department of Energy, Labor and Economic Growth, Elevator Safety Division, Elevator Rules, 2005, Incorporating ASME AI 7.1-2004.
Structural:	Michigan Department of Licensing and Regulatory Affairs, Bureau of Construction Codes, 2015 Michigan Building Code, incorporating the 2015 Edition of the International Building Code.
Mechanical:	Michigan Department of Energy, Labor and Economic Growth; Bureau of Construction Codes, 2015 Michigan Mechanical Code Incorporating the 2015 Edition of the International Mechanical Code.
	ANSI/ASHRAE/IESNA 90.1-2013 Energy Standard for Buildings Except Low-Rise Residential Buildings.
	NFPA 13 — Installation of Sprinkler Systems — 2013 Edition.
Plumbing:	Michigan Department of Energy, Labor and Economic Growth; Bureau of Construction Codes, 2018 Michigan Plumbing Code Incorporating the 2018 Edition of the International Plumbing Code.
Electrical:	Michigan Department of Licensing and Regulatory Affairs, Bureau of Construction Codes, Electrical Division, 2017 Michigan Electrical Code, incorporating the 2017 Edition of the National Electrical Code.
Fire Alarm:	2013 Edition of NFPA 72 - National Fire Alarm and Signaling Code.

### **Minimum Code Requirements**

The following is a general summary of the life safety and barrier free code requirements for all buildings utilizing current applicable codes and standards. The summary is based on the requirements for new construction, only as a benchmark to evaluate existing conditions within each building.

**Building Fire and Occupancy Separations** 

2-hour fire rated separation between different users.

#### Means of Egress and Fire Ratings

A minimum of two exits from all floors and a maximum common path of egress travel of 75 feet in non-sprinklered buildings and 100 feet in fully sprinklered buildings.

Doors shall swing in the direction of egress where serving an occupant load of 50 or more. Doors shall be equipped with panic hardware where serving an occupant load of 50 or more.

Dead end corridors cannot exceed 20 feet in length in non-sprinklered buildings and 50 feet in fully sprinklered buildings.

Maximum total exit access travel distance cannot exceed 200 feet in non-sprinklered buildings and 300 feet in fully sprinklered buildings.

The total width of a level means of egress shall not be less than the total occupant load served multiplied by a factor of 0.2" per occupant, but shall not be less than may be specified elsewhere in the code.

The total width of a means of egress stair shall not be less than the total occupant load served multiplied by a factor of 0.3" per occupant.

Rooms or spaces with an occupant load exceeding 50 or a total square footage greater than 1,000 are required to have two exits or exit access doorways.

Rooms or spaces with an occupant load exceeding 500 require a minimum of three exits.

Stairs and ramps shall have handrails on each side and shall be continuous without interruption.

Guards 42" high shall be provided at all open sided walking surfaces, stairs and ramps higher than 30" above the floor or grade below.

1-hour fire rated corridor walls with 20 minute fire rated doors are typically required in non-sprinklered buildings.

1-hour fire rated stair enclosures with 60 minute B label fire rated doors are typically required where connecting less than 4 floors.

1-hour fire rated elevator shafts and elevator equipment rooms.

Signage is required of the following:

- Tactile "EXIT" sign adjacent to each stairway egress door, exit passageway and exit discharge.
- Elevator floor designation at hoistway.
- Assembly space maximum occupant load. (Spaces with an occupant load exceeding 50.)

### Exit Signage

Exits and exit access doors shall be marked with readily visible exit signs.

Viewing distance in exit access corridor shall not exceed 100 feet.

### Emergency Egress Lighting

Lighting along all means of egress shall provide not less than an average of 1 footcandle and a minimum of 0.1 footcandle measured along the path of egress at the floor level. Furthermore, a maximum-to-minimum illumination uniformity ratio of 40 to 1 shall not be exceeded.

In the event of a power failure, an emergency electrical system shall automatically illuminate the following areas for a duration of not less than 90 minutes and shall consist of storage batteries, unit equipment or an on-site generator:

- Exit access corridors
- Exit access passageways and aisles in rooms and spaces required to have two or more exits
- Exit stairways

#### **Lighting Control**

Michigan Energy Code requires that all buildings be equipped with automatic control devices capable of shutting off light in all spaces without occupant intervention. All building spaces must comply with maximum allowable power densities as defined in ASHRAE 90.1-2013. Daylighting controls must also be utilized for applicable areas.

#### Fire Alarm Systems

Manual fire alarm system at Assembly occupancies with an occupant load of 300 or more.

Manual fire alarm system at Business occupancies with a combined occupant load of all floors greater than 500 or an occupant load of more than 100 above or below the lowest level of exit discharge.

#### Fire Suppression Systems

An automatic sprinkler system at Assembly occupancies with a fire area exceeding 12,000 square feet

#### Barrier Free Requirements

At least one accessible route shall connect accessible buildings, accessible facilities, accessible elements and accessible spaces that are on the same site. Where more than one means of egress is required, there shall be at least 2 accessible means of egress.

At least 60 percent of all building public entrances shall be accessible.

When a building or portion thereof is required to be accessible, an accessible route shall be provided to each portion of the building, to accessible building entrances connecting accessible pedestrian walkways, and a public way.

Changes in floor level between 1/4" minimum to 1/2" maximum is to be beveled with a slope no steeper than 1:2.

The minimum width of each door opening shall be sufficient for the occupant load thereof and provide a clear width of at least 32 inches.

Swinging doors must have maneuvering clearances in compliance with ICC/ANSI AI 17.1.

Door handles, pulls latches, locks and other operating devices on doors required to be accessible must not require tight grasping, tight pinching or twisting of the wrist to operate.

Code compliant signage shall be provided at the following locations:

- Accessible areas of refuge
- Accessible entrances where not all are accessible
- Directional signage at inaccessible entrances
- Unisex toilets
- Accessible toilets where not all are accessible
- Directional signage to accessible toilets at inaccessible toilets

Wall mounted or free standing protruding objects must comply with MBC.

Passenger elevators on an accessible route shall be accessible and comply with applicable provisions of the code.

Plumbing elements and facilities required to be accessible must comply with applicable provisions of the code. At least one of each type of fixture, element, control or dispenser in each accessible toilet room and bathing facility must be accessible.

### Existing Building Code Application

The legal occupancy of any structure existing on the date of adoption of the code shall be permitted to continue without change unless deemed necessary by the building official for the general safety and welfare of the occupants and the public.

Existing buildings undergoing repair, alterations or additions and change of occupancy shall be permitted to comply with the Michigan Rehabilitation Code for existing Buildings.

New work, including renovations and additions to any structure shall conform to the code requirements for new construction. Modifications and repairs shall not cause the existing structure to be in violation of the code- Portions not altered or affected by the modifications need not comply with the current building code.

### **Deferred Maintenance Budgets**

The total 5 year DMB building are as follows (refer to the building data sheets for detailed information).

Building	4	5 Year DMB
Building CA (Business and Public Services)	\$	76,633
Building CB (General Classrooms)	\$	23,200
Building CC (Library)	\$	1,734,257
Building CD (Meter)	\$	706,144
Building CE (Health and Human Services)	\$	232,943
Building CF (General Classrooms)	\$	27,550
Building CG (Student Services)	\$	1,204,209
Building CH (Student Services/classrooms)	\$	1,736,288
Building CI (Campus Police/Plant Operations)	\$	1,450,209
Building CK (Cultural Center)	\$	3,434,136
Building CL (Fine Arts)	\$	777,454
Building CM (Performing Arts)	\$	4,310,157
Building CN (General Classrooms)	\$	1,535,920
Building CP (Student Center/Bookstore)	\$	2,160,874
Building CR (Health Science Technology)	\$	1,978,133
Building CS (Administrative Center)	\$	2,571,506
Building UC-1 (Professional Development Center)	\$	5,134,806
Building UC-2 (Engineeering and Technical Center)	\$	6,745,226
Building UC-3 (Classroom and Lab Building)	\$	1,777,048
Building UC-4 (Osteopathic Medicine)	\$	1,123,976

### **Current Replacement Values**

The CRV per building are as follows:

Building CA (Business and Public Services)	37,533 SF	х	\$426 SF	=	\$15,989,058
Building CB (General Classrooms)	18,716 SF	х	\$403 SF	=	\$7,542,548
Building CC (Library)	57,502 SF	х	\$370 SF	=	\$21,275,740
Building CD (Meter)	1,562 SF	х	\$420 SF	=	\$656,040
Building CE (Health and Human Services)	63,737 SF	х	\$480 SF	=	\$30,593,760
Building CF (General Classrooms)	19,629 SF	х	\$453 SF	=	\$8,891,937
Building CG (Student Services)	19,708 SF	х	\$410 SF	=	\$8,080,280
Building CH (Student Services/Classrooms)	34,430 SF	х	\$405 SF	=	\$13,944,150
Building CI (Campus Police/Plant Operations)	16,523 SF	х	\$420 SF	=	\$6,939,660
Building CK (Cultural Center)	51,880 SF	х	\$420 SF	=	\$21,789,600
Building CL (Fine Arts)	30,400 SF	х	\$542 SF	=	\$16,476,800
Building CM (Performing Arts)	71,954 SF	х	\$585 SF	=	\$42,093,090
Building CN (General Classrooms)	65,357 SF	х	\$401 SF	=	\$26,208,157
Building CP (Student Center/Bookstore)	34,496 SF	х	\$414 SF	=	\$14,281,344
Building CR (Health Science Technology)	36,478 SF	х	\$450 SF	=	\$16,415,100
Building CS (Administrative Center)	42,055 SF	х	\$420 SF	=	\$17,663,100
Building UC-1 (Professional Development Center)	88,768 SF	х	\$417 SF	=	\$37,016,256
Building UC-2 (Engineeering and Technical Center)	53,290 SF	х	\$439 SF	=	\$23,394,310
Building UC-3 (Classroom and Lab Building)	36,718 SF	х	\$458 SF	=	\$16,816,844
Building UC-4 (Osteopathic Medicine)	25,444 SF	х	\$515 SF	=	\$13,103,660

# TAB 4

### FCI Index Table

		R	eplacement	D C	Total Deficiencies onstruction		Total Deficiencies Project	
Building	Square Feet	0	Cost (CRV)		Cost	Co	st (5 Year DMB)	FCI
Building CA (Business and Public Services)	37,533	\$	15,989,058	\$	52,850	\$	76,633	0.48%
Building CB (General Classrooms)	18,716	\$	7,542,548	\$	16,000	\$	23,200	0.31%
Building CC (Library)	57,502	\$	21,275,740	\$	1,196,039	\$	1,734,257	8.15%
Building CD (Meter)	1,562	\$	656,040	\$	486,996	\$	706,144	107.64%
Building CE (Health and Human Services)	63,737	\$	30,593,760	\$	160,650	\$	232,943	0.76%
Building CF (General Classrooms)	19,629	\$	8,891,937	\$	19,000	\$	27,550	0.31%
Building CG (Student Services)	19,708	\$	8,080,280	\$	830,489	\$	1,204,209	14.90%
Building CH (Student Services/Classrooms)	34,430	\$	13,944,150	\$	1,197,440	\$	1,736,288	12.45%
Building CI (Campus Police/Plant Operations)	16,523	\$	6,939,660	\$	1,000,144	\$	1,450,209	20.90%
Building CK (Cultural Center)	51,880	\$	21,789,600	\$	2,368,369	\$	3,434,136	15.76%
Building CL (Fine Arts)	30,400	\$	16,476,800	\$	536,175	\$	777,454	4.72%
Building CM (Performing Arts)	71,954	\$	42,093,090	\$	2,972,522	\$	4,310,157	10.24%
Building CN (General Classrooms)	65,357	\$	26,208,157	\$	1,059,255	\$	1,535,920	5.86%
Building CP (Student Center/Bookstore)	34,496	\$	14,281,344	\$	1,490,258	\$	2,160,874	15.13%
Building CR (Health Science Technology)	36,478	\$	16,415,100	\$	1,364,230	\$	1,978,133	12.05%
Building CS (Administrative Center)	42,055	\$	17,663,100	\$	1,773,453	\$	2,571,506	14.56%
Building UC-1 (Professional Development Center)	88,768	\$	37,016,256	\$	3,541,245	\$	5,134,806	13.87%
Building UC-2 (Engineeering and Technical Center)	53,290	\$	23,394,310	\$	4,651,880	\$	6,745,226	28.83%
Building UC-3 (Classroom and Lab Building)	36,718	\$	16,816,844	\$	1,225,550	\$	1,777,048	10.57%
Building UC-4 (Osteopathic Medicine)	25,444	\$	13,103,660	\$	775,156	\$	1,123,976	8.58%

• FCI is a simple measure of the relative condition of a building to its approximate replacement cost (i.e., the higher the FCI, the poorer the condition of the existing building).

# TAB 5

### 44575 Garfield Road · Clinton Twp., MI 48038-1139 · 1.866.Macomb1 · www.macomb.edu



MACOMB COMMUNITY COLLEGE

🔍 14500 E. 12 Mile Road • Warren, Michigan 48088-3896 • 1.866.Macomb1



MACOMB COMMUNITY COLLEGE

Community Center/Bookstore



MARTIN ROAD **REVISED 5/11/17** Ν C **LEGEND—MAIN BUILDINGS** L Bunert Conference Center A Boiler House & Disabled Parking Ġ. **Disabled Entrances** B Science Building M Transportation and Energy Location Location Spaces Spaces С East, West & South Technology Building C Classroom Building C-Bldg Lot 1A Staff 3 19 Main N College Park Annex .1 D Administration Building J-Bldg Lot 2 7 1 Institutional Research Κ East & West E Classroom Building Lot 3 4 K-Bldg 11 Marketing Μ East & West F Classroom Building Lot 4 11 T-Bldg 2 East Middle R Publications G Classroom, Admissions N-Bldg Lot 4 Staff 7 6 Р P Sports & Expo Center North Counseling, Financial Aid, 7 l ot 5 M-TEC Main Q Boiler House Career Services Building, 14 Lot 8 **Robert E. Turner Complex** Cashier Lot 10 18 Blue Light R Graphic Technical Building J Max Thompson Learning Lot 12 8 Emergency Phone Media Center S Walter E. Bradley Auditorium, **Wireless Available** Lot 14 9 T Mechanical Technical Building K John Lewis Student Center Lot 15 Staff 8 **Campus-Wide** (#) Elec.Vehicle Outlet College Police Dept.

East Campus 21901 Dunham Road, Clinton Township, MI 48036 • 1.866.Macomb1 • www.macomb.edu



### MACOMB COMMUNITY COLLEGE =\_,SM



# TAB 6

## BUILDING CA



### **GENERAL OVERVIEW**

75% Classroom, 10% Lab, 15% Offices
1969
37,533 SF
2
\$76,633
\$15,989,058

FCI: 0.48%

### **COMMENTS**

### **Roof System**

- Firestone EPDM roof installed in 2016.
- Roof warranty expires in 2031.

### **HVAC System**

• HVAC system was replaced in Summer 2016.

### **Plumbing System**

• Plumbing system was replaced in Summer 2016.

### **Fire Protection**

• Full fire suppression system was added in Summer 2016.

### **Temperature Controls**

• Temperature controls were replaced in Summer 2016.

### **Power Systems**

• Electrical equipment was upgraded in Summer 2016.

### **Lighting System**

• Lighting was replaced with LED fixtures and controls were added in Summer 2016.

ELECTRICAL EQUIPMENT CA 11 MECHANICAL EQUIPMENT CA 10 ן ו BUILDING "CA" BASEMENT

NORTH





### Building CA

No	Itom/Description	Location	Notos	Qty.	Unit	Archite	ectural		Mecha	anical	Elect	trical		Cons	truction	Droio	at Coat
INO.	nem/Description	Location	NOLES			Unit Cost	Subto	tal	Unit Cost	Subtotal	Unit Cost	Subt	total	C	ost	Proje	CI COSI
Enclosu	re System																
1	Enclosure System	General	Louvers on east side of building not caulked.	1	LS	\$ 1,500.00	\$ 1	,500						\$	1,500	\$	2,175
2	Enclosure System	General	Patch concrete soffit with exposed rebar at north entry.	1	LS	\$ 4,000.00	\$ 4	,000						\$	4,000	\$	5,800
3	Enclosure System	General	Repair backside of concrete parapet wall where spalling in northwest corner.	1	LS	\$ 1,500.00	\$ 1	,500						\$	1,500	\$	2,175
4	Enclosure System	General	Repair/seal crack in backside of north concrete parapet wall.	1	LS	\$ 1,500.00	\$ 1	,500						\$	1,500	\$	2,175
Finish System																	
1	Finish System	General	Caulk door from mechanical room to exterior.	1	LS	\$ 500.00	\$	500						\$	500	\$	725
2	Finish System	General	Caulk door from lower mechanical room to electrical room.	1	LS	\$ 500.00	\$	500						\$	500	\$	725
3	Finish System	General	Refinish epoxy floor in lower level electrical room.	1	LS	\$ 3,000.00	\$ 3	,000,						\$	3,000	\$	4,350
4	Finish System	General	Repair cast concrete stair treads at Stair #1.	1	LS	\$ 2,000.00	\$2	,000						\$	2,000	\$	2,900
5	Finish System	General	Repair cast concrete stair treads at Stair #2.	1	LS	\$ 2,000.00	\$ 2	,000,						\$	2,000	\$	2,900
HVAC Sy	/stem	-															
1	Jacketing/Insulation	Roof	Repair/replace portion of damaged CHW piping insulation and jacketing.	1	LS				\$ 750.00	\$ 750				\$	750	\$	1,088
Power S	ystem	-							,								
4		Cananal	Electrical equipment had no indication of maintenance or testing since original installation	4				Т			¢ 7,500,00	¢	7 500	¢	7 500	¢	40.075
1		General	in 2016. Testing / maintenance is recommended at regular intervals.	1	LS						\$ 7,500.00	Þ	7,500	\$	7,500	\$	10,875
			One of the two meters at the main switchboard is inoperable. The remaining meter														
2	Electrical Equipment	General	displayed maximum values that exceeded expected ranges by a significant amount.	1	LS						\$ 12,000.00	\$ 1	2,000	\$	12,000	\$	17,400
			Further testing & investigation is recommended.														
2	Electrical Equipment	Conorol	NFPA / UE requires updating arc flash studies at an interval hol to exceed 5 years. The	1	18						¢ 7,000,00	¢	7 000	¢	7 000	¢	10 150
3		General	the building-wide power systems study		L3						\$ 7,000.00	φ	7,000	φ	7,000	φ	10,150
			Various i-boxes were observed with missing coverplates and exposed wiring. This is a								<b>.</b>			•		<u> </u>	
4	Utility Spaces	Mechanical/Electrical Rooms	code violation. It is recommended this be corrected.	1	LS						\$ 500.00	\$	500	\$	500	\$	725
Lighting	System				-			_	,		-						
1	Lighting System	General	Various areas with damaged or inoperable fixtures were observed. (stairwell fixture lens,	Λ	FΔ						\$ 400.00	\$	1 600	\$	1 600	\$	2 320
1		General	conf rm 210 fixtures, classroom 202 fixtures) Replace/repair damaged lighting fixtures	4							φ 400.00	Ψ	1,000	Ψ	1,000	Ψ	2,520
Codes S	ystems and Barrier Free			-	_												
1	Code Systems and Barrier Free	General	Stoop at door from mechanical room to exterior is too low; needs to be at floor elevation.	1	LS	\$ 7,000.00	\$ 7	,000			<u> </u>			\$	7,000	\$	10,150
							\$ 23	,500		\$ 750		\$2	28,600	\$	52,850	\$	76,633

## BUILDING CB



### **GENERAL OVERVIEW**

- Use: Classrooms and Offices
- Year Built: 1968
- Total Area: 18,716 SF
- Floors: 1
- 5 Year DMB: \$23,200
- CRV: \$7,542,548
- FCI: 0.31%

### **COMMENTS**

### **Roof System**

- Firestone EPDM roof installed in 2017.
- Roof warranty expires in 2032.

### **HVAC System**

• HVAC systems were replaced in 2019.

### **Plumbing System**

• Plumbing systems were replaced in 2019.

### **Temperature Controls**

• Temperature controls were replaced in 2019.

### **Power Systems**

• Electrical equipment was upgraded in 2019 and is good condition.

### Lighting System

• Lighting and controls were upgraded in 2019 and are in good condition.







### Building CB

No	Itom/Description	Location				Otr	Otr	Linit	Archite	Architectural		Mechanical		trical	Const	truction	Draiget (	Coat
INO.	item/Description	Location	Notes	Qty.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	С	ost	Project C	Jost			
Enclosu	Enclosure System																	
1	Enclosure System	General	Precast concrete soffit have rusted exposed rebar.	1	LS	\$ 3,000.00	\$ 3,000					\$	3,000	\$4	1,350			
2	Enclosure System	General	Sealants dried and cracking at control joints.	1	LS	\$ 5,000.00	\$ 5,000					\$	5,000	\$7	,250			
3	Enclosure System	General	Patch hole in brick where conduit removed.	1	LS	\$ 1,000.00	\$ 1,000					\$	1,000	\$1	,450			
4	Enclosure System	General	Precast concrete piers have rusting exposed rebar.	1	LS	\$ 3,000.00	\$ 3,000					\$	3,000	\$4	1,350			
Power S	ystems											_						
1	Power Systems	General	Existing arc flash labels are generic type and do not indicate incident energy boundaries, available fault current, etc While not required by code, it is recommended to update power system study and labeling to match that of building CA (Note: CB is sub-fed from CA)	1	LS					\$ 4,000.00	\$ 4,000	\$	4,000	\$5	5,800			
-		-		_			\$ 12,000	-	\$-		\$ 4,000	) \$	16,000	\$ 23	3,200			

## **BUILDING CC**



### **GENERAL OVERVIEW**

Use:	Library

Total Area: 57,502 SF

1969

- Floors: 2

Year Built:

- 5 Year DMB: \$1,734,257 CRV: \$21,275,740
- FCI: 8.15%

### **COMMENTS**

### **Roof System**

- Trocal single-ply roof installed in 1994.
- Roof warranty expired in 2002.
- Entire roof should be scheduled for replacement.

### **HVAC System**

• Mechanical system was renovated Summer 2017 (reconditioned air handling units and replaced equipment).

### **Temperature Controls**

• Temperature controls were replaced in 2017.

### Lighting System

• Lighting and controls were upgraded in 2017 and are in good condition.


Existing Substation



Existing Distribution Equipment





# Building CC

NL	lkaur (Daar aufin ti au	L tion	Notos	01.	1.1	Archit	ectural	Mecha	anical	Elect	Electrical		Construction		-+ 0 +
INO.	item/Description	Location	Notes	Qty.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal		Cost	Proj	Ct Cost
Roof Sys	stem														
1	Roof System	Roof	Replace membrane roof.	38,500	SF	\$ 15.00	\$ 577,500					\$	577,500	\$	837,375
Enclosu	re System								-						
1	Enclosure System	General	Glass block windows are leaking in two (2) locations.	1	LS	\$ 2,000.00	\$ 2,000					\$	2,000	\$	2,900
2	Enclosure System	General	Sealants dried and cracking at control joints.	1	LS	\$ 10,000.00	\$ 10,000					\$	10,000	\$	14,500
3	Enclosure System	General	Tuckpoint facebrick and precast concrete.	1	LS	\$ 5,000.00	\$ 5,000					\$	5,000	\$	7,250
4	Enclosure System	General	Cast concrete below arched window sills are cracking.	1	LS	\$ 5,000.00	\$ 5,000					\$	5,000	\$	7,250
5	Enclosure System	General	Replace door seals at mechanical/electrical room exterior doors.	1	LS	\$ 1,500.00	\$ 1,500					\$	1,500	\$	2,175
Finish S	ystem								-						
1	Finish System	General	Replace epoxy flooring in mechanical rooms.	1	LS	\$ 10,000.00	\$ 10,000					\$	10,000	\$	14,500
2	Finish System	General	Repair gypsum board sofffits.	1	LS	\$ 1,500.00	\$ 1,500					\$	1,500	\$	2,175
3	Finish System	General	Repair vinyl wall covering.	1	LS	\$ 1,500.00	\$ 1,500					\$	1,500	\$	2,175
Plumbin	g System			<u> </u>						•					
		<b>I</b>	Portion of the domestic cold water distribution piping system is galvanized steel. Due to its					<b>.</b>		i – – – – –		T.			
1	Plumbing System	Building	age the piping is showing signs of deterioration and should be replaced.	60	Lŀ			\$ 55.00	\$ 3,300			\$	3,300	\$	4,785
2	Plumbing System	Ruilding	Portion of the cold and hot water piping has missing and damaged insulation. The	10 701	QE			¢ 0.77	¢ 15.220			¢	15 220	¢	22.007
2		Building	insulation should be replaced .	19,791	35			φ 0.77	φ 15,259			φ	15,259	φ	22,097
Power S	ystems								-					_	
			Main electrical equipment from 1993 addition. This equipment is nearing the end of its life												
1	Power Systems	Electrical Room C171	expectancy and should be considered for replacement in the next renovation (MV	1	LS					\$415,000.00	\$ 415,000	) <b>\$</b>	415,000	\$	601,750
			switches, I ransformer, main switchboard, distribution panels and branch panelboards).									╉───			
2	Power Systems	Electrical Room C104	Legacy equipment from the original 1968 building is passed it's life expectancy and should be replaced with the past repovetion	1	LS					\$121,000.00	\$ 121,000	) <b>\$</b>	121,000	\$	175,450
			Existing arc flash labels are generic type and do not indicate incident energy boundaries									+			
3	Power Systems	General	available fault current, etc., While not required by code, it is recommended to update	1	LS					\$ 4.000.00	\$ 4.000	) <b>\$</b>	4.000	\$	5.800
-			power system study and labeling to match that of building CA.							<b>,</b> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	+ ,	Ŧ	.,	Ť	-,
			Most of the electrical equipment had no indication of maintenance or testing since original												
4	Power Systems	General	installation, while the main electrical equipment was last tested in 2013. Testing /	1	LS					\$ 7,500.00	\$ 7,500	<i>i</i> \$	7,500	\$	10,875
			maintenance is recommended at regular intervals.												
Code Sy	stems and Barrier Free									-				_	
1	Code Systems and Barrier Free	Stairs	Guard rails are not compliant with current code. Balluster spacing greater than 4". No	2	EA	\$ 7,500.00	\$ 15,000					\$	15,000	\$	21,750
2	Code Systems and Barrier Free	Stairs	Valle fall where below 60.	1	19	¢ 1,000,00	¢ 1,000			╂───┤			1 000	¢	1 460
2	Coue Systems and Damer Free	StallS		I	٢۶	φ 1,000.00	φ 1,000		¢ 40.500	<u> </u>	¢ E 47 E 00		1,000	ې د ۱	1,450
							<b>ъ 630,000</b>		ə 18,539		→ 547,500	/ \$ 1	1,196,039	<b>\$</b> 1	134,251

# **BUILDING CD**



# **GENERAL OVERVIEW**

Use: Meter

Year Built:

- Total Area: 1,562 SF
- Floors: 1 5 Year DMB: \$706,144
- CRV: \$656,040
- FCI: 107.64%

# **COMMENTS**

# **Roof System**

• Roof replaced in 1998.

# **HVAC System**

- Ventilation added for the transformer room in Summer 2013.
- Electrical unit heaters were replaced in approximately 2019.

# **Temperature Controls**

• Controls added to the transformer room ventilation in Summer 2013.



Existing Switchgear







# Building CD

No	Itom/Description	Logation	Notos	Otv	Unit	Archite	Architectural		anical	Elect	rical	Construction	Draiget Cost
NO.	Item/Description	Location	Notes	Qty.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	Cost	Project Cost
Power S	ystems												
1	Power Systems	Main Electrical Room	MV Switch lineup appears to have been installed at different intervals of time, ranging from 2004, 1993 and 1969. Switches from 1993 and earlier are nearing or past life expectancy and should be considered for replacement within the next renovation.	7	EA					\$ 60,000.00	\$ 420,000	\$ 420,000	\$ 609,000
2	Power Systems	Main Electrical Room	Secondary power panels, transformers and disconnects serving the receptacles, lighting, heating, ventilation of building CD appears original from 1968. This equipment is passed it's life expectancy and should be replaced with the next renovation.	1	LS					\$ 40,000.00	\$ 40,000	\$ 40,000	\$ 58,000
3	Power Systems	Main Electrical Room	Pullbox was observed with partially open cover and exposed wiring. This is a code violation. It is recommended this be corrected.	1	LS					\$ 500.00	\$ 500	\$ 500	\$ 725
4	Power Systems	General	Existing arc flash labels are generic type and do not indicate incident energy boundaries, available fault current, etc While not required by code, it is recommended to update power system study and labeling to match that of Building CA.	1	LS					\$ 4,000.00	\$ 4,000	\$ 4,000	\$ 5,800
5	Power Systems	General	The electrical equipment had no indication of recent maintenance or testing. The labels indicate the latest testing was done in 2013 on the equipment. Testing / maintenance is recommended at regular intervals.	1	LS					\$ 10,000.00	\$ 10,000	\$ 10,000	\$ 14,500
Lighting	System									-		-	
1	Lighting System	General	Lighting consists of fluorescent fixtures containing T12 lamps. Lighting should be replaced throughout with LED.	1,562	SF					\$ 8.00	\$ 12,496	\$ 12,496	\$ 18,119
											\$ 486,996	\$ 486,996	\$ 706,144

# **BUILDING CE**



#### **GENERAL OVERVIEW**

Use:	Classrooms,	Labs and	Offices
	,		

Year Built: 1981

Total Area: 63,737 SF

- Floors: 2
- 5 Year DMB: \$232,943
- CRV: \$30,593,760
- FCI: 0.76%

#### **COMMENTS**

# **Roof System**

- Johns Manville EPDM room installed in 2013.
- Roof warranty expires in 2028.

#### **Finish System**

All finishes have been updated.

#### **HVAC System**

• HVAC systems were replaced in 2018.

#### **Plumbing System**

• Plumbing and medical gas systems were replaced in 2018.

### **Temperature Controls**

• Temperature controls were replaced in 2018.

#### **Power Systems**

• Medium voltage switches and pad mounted transformer were upgraded in 2018 and appear in good condition.

#### **Lighting System**

• Lighting and controls were upgraded in 2018 and are in good condition.

#### **Code Systems and Barrier Free**

• Tiered lecture hall seating does not have barrier free space allocated throughout the space. No action required.



Existing Generator



Existing Distribution Equipment

BUILDING "CE" 100 LEVEL







BUILDING "CE" 200 LEVEL

NORTH

# Building CE

No	Itom/Deceription	Location	Notoo	Otr	Linit	Archite	Architectural Mechanical		Elec	Electrical		nstruction	Draiget	Cast	
INO.	item/Description	Location	Notes	Qiy.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal		Cost	Project	Cost
Enclosu	re System														
1	Enclosure System	West Side	Soffits on west side of building have water damage.	1	LS	\$ 2,000.00	\$ 2,000					\$	2,000	\$	2,900
HVAC S	ystem														
1	HVAC System	Building	Replace roof mounted exhaust fan (no fan identification) with Greenheck model GB-071.	1	EA			\$ 750.0	0 \$ 7	50		\$	750	\$	1,088
Power S	Systems	-								-					
1	Power Systems	Electrical Room E213	Main switchboard and electrical distribution equipment appear to have been installed in 1981. This equipment is past it's life expectancy and should be considered for replacement within the next renovation.	1	LS					\$130,000.00	\$ 130,00	)0 \$	130,000	\$ 18	\$8,500
2	Power Systems	Courtyard	60kW Natural Gas Generator manufactured date: 2003, with 955 running hours. Generators purpose is to back up MDF equipment and doesn't appear to serve life safety loads. Last indication of maintenance on the generator was noted to be in 2016. Battery date code indicates it was manufactured in 2007. Testing / maintenance is recommended at regular intervals.	1	LS					\$ 7,500.00	\$ 7,50	)0 \$	7,500	\$ 1	0,875
3	Power Systems	Mechanical E101	ATS appears to have been installed in 2004. The latest testing date is not legible. The cover of the Generator Annunciator Panel is not secure and should be corrected. Testing / maintenance is recommended at regular intervals.	1	LS					\$ 1,000.00	\$ 1,00	)0 \$	1,000	\$	1,450
4	Power Systems	Connector	ADA pushbutton covers (interior and exterior) are loose, and conductors are visible. These were possibly undergoing maintenance during the site visit.	4	EA					\$ 250.00	\$ 1,00	)0 \$	1,000	\$	1,450
5	Power Systems	General	Existing arc flash labels are generic type and do not indicate incident energy boundaries, available fault current, etc While not required by code, it is recommended to update power system study and labeling to match that of Building CA.	1	LS					\$ 4,000.00	\$ 4,00	)0 \$	4,000	\$	5,800
6	Power Systems	General	Electrical equipment had no indication of maintenance or testing since original installation in 1981. Testing / maintenance is recommended at regular intervals.	1	LS					\$ 10,000.00	\$ 10,00	)0 \$	10,000	\$ 1	4,500
Lighting	J System														
1	Lighting System	IDF Closet E213-2	Lighting consists of fluorescent fixtures containing T8 lamps. Lighting should be replaced with LED.	1	LS					\$ 400.00	\$ 40	)0 \$	400	\$	580
Code Sy	stems and Barrier Free														
1	Code Systems and Barrier Free	Stairwells - First Floor	No guard rail protection for stringers below 80".	4	EA	\$ 1,000.00	\$ 4,000					\$	4,000	\$	5,800
							\$ 6,000		\$ 75	50	\$ 153,90	)0 \$	160,650	\$ 23	2,943

# BUILDING CF



### **GENERAL OVERVIEW**

Use:	Classrooms and Lab
Use:	Classrooms and Lap

- Year Built: 1970
- Total Area: 19,629 SF
- Floors: 1
- 5 Year DMB: \$27,550 CRV: \$8,891,937
- FCI: 0.31%

# **COMMENTS**

# **Roof System**

- Firestone EPDM roof installed in 2015.
- Roof warranty expires in 2030.

# **Finish System**

• Finishes updated in 2015.

# **HVAC System**

• All new HVAC equipment provided including ductwork in Summer 2015.

#### **Plumbing System**

• Plumbing replaced in Summer 2015.

#### **Fire Protection**

• Fire rated walls in lieu of automatic fire suppression system were added in 2015.

#### **Temperature Controls**

• Temperature controls replaced in Summer 2015.

#### **Power Systems**

• Electrical equipment was upgraded in 2015 and is in good condition.

BUILDING "CF" 100 LEVEL

NORTH



# Building CF

No	Itom/Description	Location	Notos	Otr	Linit	Archite	ctural	Mech	anical	Electrical		Construct	ion 🛛 🗖	raiaat Caat
INO.	item/Description	Location	Notes	Qiy.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	Cost	P	roject Cost
Enclosu	re System													
1	Enclosure System	General	Patch holes in wall on north, east and west elevations.	3	EA	\$ 1,000.00	\$ 3,000					\$3,	000 \$	4,350
2	Enclosure System	General	Concrete soffit on west elevation is cracked.	1	LS	\$ 1,500.00	\$ 1,500					\$1,	500 \$	2,175
HVAC Sy	ystem													
1	HVAC System	General	Corrosion at seals of CF CP-1 and CP-2 was observed. Plan for replacement I near future.	2	EA			\$ 1,500.00	\$ 3,00	0		\$3,	000 \$	4,350
Power S	ystems													
1	Power Systems	General	Existing arc flash labels are generic type and do not indicate incident energy boundaries, available fault current, etc While not required by code, it is recommended to update power system study and labeling to match that of Building CA.	1	LS				\$	- \$ 4,000.00	\$ 4,000	\$4,	000 \$	5,800
2	Power Systems	General	Electrical equipment had no indication of maintenance or testing since original installation in 2015. Testing / maintenance is recommended at regular intervals.	1	LS				\$	- \$ 7,500.00	\$ 7,500	\$7,	500 \$	10,875
							\$ 4,500		\$ 3,00	0	\$ 11,500	\$ 19,	000 \$	27,550

# BUILDING CG



#### **GENERAL OVERVIEW**

- Use: Student Services
- Year Built: 1969, 2012 Renovation
- Total Area: 19,708 SF
- Floors: 1 5 Year DMB: \$1,204,209
- CRV: \$8,080,280
- FCI: 14.90%

#### **COMMENTS**

#### **Roof System**

- Firestone EPDM roof installed in 2018.
- Roof warranty expires in 2033.

#### **HVAC System**

- All new HVAC system installed in 2012.
- Existing rooftop units were refurbished. RTU G-1 and RTU G-2, Seasons-4, DX cooling with gas heat (multi-zone). Originally installed in 2005, 18 years old. Median useful life expectancy

#### **Plumbing System**

• Toilets renovated and piping replaced in 2012.

#### **Fire Protection**

• Corridors were fire rated in lieu of adding fire suppression.

#### **Temperature Controls**

• Replace existing Continuum (Andover) BAS controls with new Tridium (Honeywell) system.

#### **Power Systems**

- Electrical equipment was upgraded in 2012 and is good condition.
- The existing generator serves a single automatic transfer switch which already serves optional standby loads. The generator will not be permitted to also serve future life safety loads without distribution system modifications.

# Lighting System

- Lighting and controls were upgraded in 2012 and are in good condition. The majority of the existing light fixtures utilize T8 fluorescent lamps. Emergency lighting is provided via batteries. Within the next renovation, new LED lighting and controls should be included to meet current ASHRAE standards, and emergency lighting should be provided for all exterior egress landings and for exterior egress paths.
- Exit signs are LED.

<u>BUILDING "CG" 100 LEVEL</u>

(NORTH



# Building CG

No	Itom/Description	Logation	Notos	Architectural		ectural	Mecha	nical	Electrical			struction	Project Cost	
INO.	item/Description	Location	Notes	Qiy.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal		Cost	Project Cost
Roof Sys	stem													
1	Roof System	General	Review roof at covered walkway; signs of water infiltration in piers.	1	LS	\$ 2,000.00	\$ 2,000					\$	2,000	\$ 2,900
BAS Sys	stem	_						_						
1	BAS System	General	Replace existing Continuum (Andover) BAS controls with new Tridium (Honeywell).	19,708	SF			\$ 10.00	\$ 197,080		\$-	- \$	197,080	\$ 285,766
HVAC S	ystem													
1	Multizone Rooftop Air Handling Unit	Roof	Replace nominal 40 ton DX/gas rooftop unit.	1	EA			\$ 265,000.00	\$ 265,000		\$ -	- \$	265,000	\$ 384,250
Power S	ystems													
1	Power Systems	General	Electrical equipment had no indication of maintenance or testing since original installation	1	LS					\$ 7,500.00	\$ 7,500	) \$	7,500	\$ 10,875
			Fin 2012. Testing / maintenance is recommended at regular intervals.									_		
2	Power Systems	General	available fault current, etc While not required by code, it is recommended to provide power system study and labeling to match that of building CA	1	LS					\$ 4,000.00	\$ 4,000	) \$	4,000	\$ 5,800
3	Power Systems	General	A convenience receptacle on the roof is missing a cover.	1	LS					\$ 165.00	\$ 165	5 \$	165	\$ 239
Lighting	System	·		·				· · · · ·				-		
1	Lighting System	General	Lighting consists of fluorescent fixtures. Lighting should be replaced with LED.	19,708	SF		\$ -		\$-	\$ 18.00	\$ 354,744	\$	354,744	\$ 514,379
	-	-					\$ 2,000	<b>-</b>	\$ 462,080		\$ 366,409	) \$	830,489	\$ 1,204,209

# **BUILDING CH**



#### **GENERAL OVERVIEW**

Use:	Classrooms and Student Services
Year Built:	1968
Total Area:	34,430 SF
Floors:	2
5 Year DMB:	\$1,486,671
CRV:	\$13,944,150
FCI:	10.66%

#### **COMMENTS**

#### **Roof System**

• Trocal single-ply roof installed in 1998. Roof warranty expired in 2010. Upper roof was recently replaced. Lower roof should be scheduled for replacement.

# Elevator

• Elevator, including machine and cab, should be replaced.

#### **HVAC System**

• All new HVAC system installed in 2011. HVAC systems should be retro-commissioned.

#### Plumbing System

• Toilets renovated and piping replaced in 2011.

#### **Fire Protection**

• Fire suppression added in 2011.

#### **Temperature Controls**

• Replace existing Desigo (Siemens) BAS controls with new Tridium (Honeywell) system.

#### **Power Systems**

• Electrical equipment was upgraded in 2011 and is good condition.

### **Lighting System**

- Lighting and controls were upgraded in 2011 and are generally in good condition. The majority of the existing light
  fixtures utilize fluorescent lamps. Emergency lighting is provided via batteries. Within the next renovation, new LED
  lighting and controls should be included to meet current ASHRAE standards, and emergency lighting should be
  provided for all exterior egress landings.
- Exit signs are LED.

- North Lobby: Emergency lighting levels in this area are likely below code minimum. Revision costs are included in Lighting item 1, above.
- South Lobby: Emergency lighting levels in this area are likely below code minimum. Revision costs are included in Lighting item 1, above.
- Building Entrances: Lights at building entrances generally need to be cleaned.

BUILDING "CH" 100 LEVEL

NORTH



BUILDING "CH" 200 LEVEL



# **Building CH**

Nie	Item /Decemintion	Location	Notos	0.5	Linit	Archite	ctural	Mec	nanical	al Electrical		Construction		Project Cost
INO.	lien/Description	Location	Notes	Qty.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	Cost	7	Toject Cost
Architec	tural System							-						
1	Elevator	General	Replace elevator equipment and cab.	1	LS	\$140,000.00	\$ 140,000					\$ 140,	000 \$	203,000
2	Roof	Roof	Replace roof on lower section	30,730	SF	\$ 14.00	\$ 430,220			1		\$ 430,	220 \$	623,819
HVAC Sy	vstem		•											
1	HVAC System	General	Recommend adding supplemental split system A/C unit to serve IDF Closet H120.	1	LS			\$ 2,500.0	\$ 2,500			\$2,	500 \$	, 3,625
2	HVAC System	General	Repair/replace boiler stack on roof; currently plastic wrapped.	1	LS			\$ 750.0	\$ 750			\$	750 \$	1,088
з	HV/AC System	Building	Perform a mechanical systems retro commissioning to restore the building mechanical	34 430	SE			\$ 5.0	\$ 172 150	1		¢ 172	150 ¢	2/0.618
5		Duilding	systems back to the orginal desing intent and complete air and water system balance	54,450	51			φ 5.00	φ 172,150	<sup>1</sup>		ψ 172,	150 φ	249,010
BAS Sys	tem								-					
1	Building Controls Systems	General	Replace existing Desigo (Siemens) BAS controls with new Tridium (Honeywell).	34,430	SF			\$ 10.0	\$ 344,300			\$ 344,	300 \$	499,235
Power S	ystems				_	_								
1	Power Systems	General	Electrical equipment had no indication of maintenance or testing since original installation	1	IS					\$ 7,500,00	\$ 7,500	\$ 7	500 \$	10 875
			in 2011. Testing / maintenance is recommended at regular intervals.		20					¢ 1,000.00	φ 1,000	ф I,	,	
2	Dower Systems	Caparal	Existing arc flash labels are generic type and do not indicate incident energy boundaries,	1	10					¢ 1,000,00	¢ 4.000	¢ 4	000 ¢	5 800
2	Power Systems	General	nower system study and labeling to match that of building CA	1	L3					φ 4,000.00	φ 4,000	<b>ֆ</b> 4,0	700 \$	5,600
3	Power Systems	General	Several clocks in the building are not master system clocks. Quantity is approximate	12	FA					\$ 1,000,00	\$ 12,000	\$ 12	000 \$	17 400
			A junction box on the roof near a mechanical unit is connected to a long length of flexible						1	¢ 1,000.00	¢ 12,000	φ 1 <u>2</u> ,	<del>,000                                  </del>	
4	Power Systems	Roof	conduit that is not properly supported and not suitable for the exterior, wet location.	1	LS					\$ 3,000.00	\$ 3,000	\$ 3,0	JOO \$	4,350
5	Power Systems	Elevator	Re-work power and controls as required to support elevator replacement	1	LS					\$ 25,000.00	\$ 25,000	\$ 25,	000 \$	, 36,250
Lighting	System													
1	Lighting System	General	Lighting consists of fluorescent fixtures. Lighting should be replaced with LED.	34,430	SF					\$ 18.00	\$ 619,740	\$ 619,	740 \$	898,623
2	Lighting System	Dean of Students H114	Lighting in the Dean of Students office is LED, however there is a mix of color	1	LS					\$ 3,500.00	\$ 3,500	\$3,	500 \$	5,075
			temperatures, making the light from approximately (3) light fixtures appear to be more blue.							'				
3	Lighting System	West Lobby (Exterior)	An exterior light fixture outside the West Lobby was on during the day. The photocell that is	1	EA					\$ 1.000.00	\$ 1.000	\$ 1.	\$ 000	1.450
		, (,	attached to the fixture may have failed.	· ·						+ ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	+ .,	<u> </u>		
Code Sy	stems and Barrier Free								1					
1	Code Systems and Barrier Free	Stairwells - First Floor	No cane rail protection for stringers below 80".	2	EA	\$ 1,000.00	\$ 2,000			<u> </u>		\$ 2,0	JOO \$	2,900
							\$ 2,000		\$ 519,700		\$ 675,740	\$   1,197,	440 \$	1,736,288

# **BUILDING CI**



#### **GENERAL OVERVIEW**

, Shops

- Year Built: 1970
- Total Area: 16,523 SF
- Floors: 1.5
- 5 Year DMB: \$1,450,209
- CRV: \$6,939,660
- FCI: 20.90%

# **COMMENTS**

# **Roof System**

• Johns Manville roof installed in 2003. Roof warranty expired in 2018. Roof should be scheduled for replacement.

# HVAC System

• Furnace F-3 was recently replaced (2022). All other major equipment appears to be original from 2003. Consider adding air conditioning to Level 1 shop areas; occupants noted uncomfortable heat during summer months.

#### **Plumbing System**

• Domestic water heaters replaced in 2019. All other plumbing systems appear to be original from 2003.

# **Temperature Controls System**

• Replace existing Desigo (Siemens) BAS controls with new Tridium (Honeywell) system.

#### **Power Systems**

• Electrical equipment was installed in 2003 and is in good condition.

# **Lighting System**

- Exit signs are LED.
- Stair 142/204: All lights were off in Stair 142/204 with no apparent local means of control. Revision costs are included in Lighting Item 1 on attached cost spreadsheet.
- Emergency lighting levels and emergency lighting controls are not compliant with current codes. Revision costs are included in Lighting Item 1 on attached cost spreadsheet.
- Paint Shop 128: LED lighting is installed in the Paint Shop, but the light level is too low. Revision costs are included in Lighting Item 1 on attached cost spreadsheet.
- Electrical Storage 140: LED panels have been installed in Elec Storage 140, however, light levels are too low. Revision costs are included in Lighting Item 1 on attached cost spreadsheet.

• Office 134: LED light fixtures have been installed in Office 134, however, light levels are too low and the color temperature is inconsistent with the rest of the building. Revision costs are included in Lighting Item 1 on attached cost spreadsheet.

- Toilet Rooms: Normal lighting levels in some Toilet Room stalls are low. Revision costs are included in Lighting Item 1 on attached cost spreadsheet.
- Squad Room 105: Downlights are not operational. Revision costs are included in Lighting Item 1 on attached cost spreadsheet.
- Corridor 102: A number of light fixtures in this main corridor are not functional. Revision costs are included in Lighting Item 1 on attached cost spreadsheet.

BUILDING "CI" 100 LEVEL





STORAGE CI 207 BUILDING "CI" 200 LEVEL


## Building CI

No.LocationLocationNotesOttesOttesUnit CostSubtotalUnit Cost <th< th=""><th>Project Cost   00 \$ 2,900   22 \$ 335,417   00 \$ 2,900   10 \$ 2,900   10 \$ 68,585   12 \$ 33,063</th></th<>	Project Cost   00 \$ 2,900   22 \$ 335,417   00 \$ 2,900   10 \$ 2,900   10 \$ 68,585   12 \$ 33,063
Roof System     1   Roof System   Roof   Clean and seal translucent panels at entries.   1   LS   \$ 2,000.00   \$ 2	00   \$ 2,90(     22   \$ 335,417     00   \$ 2,90(     00   \$ 2,90(     00   \$ 68,585     10   \$ 68,585     12   \$ 33,063
1Roof SystemRoofClean and seal translucent panels at entries.1LS\$ 2,000.00\$ 2,0	00   \$ 2,90(     22   \$ 335,417     00   \$ 2,900     00   \$ 2,900     00   \$ 68,585     10   \$ 68,585     12   \$ 33,063
1Roof SystemRoofRepalce roofRepalce roof16,523LS\$ 14.00\$ 231,322Image: Constraint of the systemSecond of the system1Finish SystemMezanineNumerous cracks in mezzanine floor should be repaired and control joints added.1LS\$ 2,000.00\$ 2,000 <t< td=""><td>22 \$ 335,417 00 \$ 2,900 10 \$ 68,585 12 \$ 33,063</td></t<>	22 \$ 335,417 00 \$ 2,900 10 \$ 68,585 12 \$ 33,063
Finish System   Finish System   I   LS   \$ 2,000.00   \$ 2,000 <td>)0 \$ 2,900 )0 \$ 68,585 )2 \$ 33,063</td>	)0 \$ 2,900 )0 \$ 68,585 )2 \$ 33,063
1Finish SystemMezzanineNumerous cracks in mezzanine floor should be repaired and control joints added.1LS\$ 2,000.00\$ 2,000	00 \$ 2,900   00 \$ 68,585   12 \$ 33,063
	)0 \$ 68,585 )2 \$ 33,063
HVAC System	)0 \$ 68,585 12 \$ 33,063
Perform mechanical system retro-commissioning to restore the building mechanical	00     \$     68,58!       12     \$     33,063
1 HVAC System Building system back to the original design intent and complete an air and water system balance 1 LS \$47,300.00 \$47,300 \$ 47,300	12 \$ 33,063
report to identify potential operational issues.	)2 \$ 33,063
2 HVAC System Building Implementation of the recommendations that come out of retro-commissioning activities. 16,523 SF \$\$ 1.38 \$\$ 22,802 \$\$ 22,802	
Temperature Controls	
Replace existing Desigo (Siemens) BAS controls with new Tridium (Honeywell) system.	
1 Temperature Controls Building Commission controls, replace pneumatic operators with electric, calibrate devices, review 16,523 SF \$ 4.83 \$ 79,806 \$ 79	)6 \$ 115,719
sequences of operation, etc.	
Power Systems	
Life Safety and Optional Standby emergency loads are served from the single 100A	
1 Power Systems General General General S 75.000.00 \$ 75.000 \$ 75.	00 \$ 108.750
Electrical Code. A second ATS dedicated to Optional Standby Loads should be added and	. ,
IDADS SNOULD DE redistributed.	
2 Power Systems General Genera	)0 \$ 18,125
Arc flash hazard warning labels are generally not installed on distribution equipment.	
3 Power Systems General General General General General General States are required by code (at minimum). While not required by code, it is 1 LS	00 \$ 5,800
recommended to update provide system study and labeling to match that of building CA.	. ,
The 30 kW natural gas generator is approaching 20 years old. The useful life of a	
4 Power Systems Outdoor Generator Concentration State Concentratio	0 \$ 130.500
capacity to serve all code-required emergency lighting and additional optional standby	φ 100,000
loads.	
5 Power Systems Mechanical Room 202 Panelboard RP-MECH has insufficient clearance from side to side 1 LS \$ 8,000.00 \$ 8,000 \$ 8	11,600
Lighting System	
In general, lighting consists of fluorescent fixtures containing 18 lamps. Lighting should be	
1 Lighting System General Gene	14 \$ 431,250
Some areas have already been retrollited to LED, such as the Garage (2950 sqit) and	
Paint is peeling from HID parking lot lighting fixtures. Provide new LED light fixtures and	
2 Lighting System Exterior 16 EA \$ 8,000.00 \$ 128,0000 \$ 128,0000 \$ 128,000 \$ 128,000	0 \$ 185,600
\$ 235 322 \$ 149 908 \$ 614 914 \$ 1 000	44 \$ 1,450 200

# BUILDING CK



Year Built: 1976

Total Area: 51,880 SF

Floors: 1

5 Year DMB: \$3,434,136 CRV: \$21,789,600

FCI: 15.76%

#### **COMMENTS**

#### Roof System (High)

- Firestone EPDM roof installed in 2016.
- Roof warranty expires in 2031.

#### Roof System (East)

- Duro-Last single-ply roof installed in 2005.
- Roof warranty expired in 2020.

#### Roof System (West)

- Johns Manville single-ply roof installed in 2010.
- Roof warranty expires in 2025.

#### **HVAC Systems**

- Existing rooftop HVAC units (3) have exceeded their useful life and should be replaced.
- Steam heating system serving connector, including steam boiler, should be removed and replaced with electric heat.

#### **Temperature Controls**

• Replace existing Desigo (Siemens) BAS controls with new Tridium (Honeywell) system.

#### **Power Systems**

- Most electrical equipment was upgraded in 2005 and that equipment is generally in good condition. The 25 kW Kohler natural gas generator located on the roof was also installed at that time to serve emergency lighting in 80% of the building area.
- Roof: Roof disconnect switches for mechanical equipment are extremely rusty and should be replaced. Revision cost is included in Power Systems Item 8 on attached cost spreadsheet.

#### Lighting System

- Lighting and controls were upgraded in 2005 in about 80% of the building area and are generally in good condition. The majority of the existing light fixtures utilize T8 and compact fluorescent lamps. Emergency lighting is provided via the emergency generator in these areas. Within the next renovation, new LED lighting and controls should be included to meet current ASHRAE standards.
- Exit signs are LED.



Existing Outdoor Primary Switch and Transformer



## Building CK

NI-	ltana (Daganin tian	Leasting	Nata	0.5	11	Archite	Architectural		anical	Elec	trical	Construct	ion ,	
NO.	Item/Description	Location	Notes	Qty.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	Cost		Project Cost
Roof Sys	stem													
1	Roof System	North Entrance	Check for roof leaks around translucent roof panels at north entrance.	1	LS	\$ 2,000.00	\$ 2,000					\$2,	000	5 2,900
Enclosu	re System									-		-		
1	Enclosure System	General	Sealants dried and cracking at control joints	1	LS	\$ 4,000.00	\$ 4,000					\$4,	000	5,800
2	Enclosure System	Southeast Corner	Repair cracked brick at overhead door (Storage CK111) - possible bearing issue	1	LS	\$ 5,000.00	\$ 5,000					\$5,	000	5 7,250
3	Enclosure System	Connector to Building CM	Tuck point and repair brick	1	LS	\$ 2,000.00	\$ 2,000					\$2,	000 \$	5 2,900
4	Enclosure System	Southwest Corner	Clean brick at SW corner of building - possible roof leak	1	LS	\$ 500.00	\$ 500					\$	500 \$	<u> </u>
5	Enclosure System	Kitchen	Replace rusted door & frames to loading dock	1	LS	\$ 2,500.00	\$ 2,500					\$2,	500 \$	3,625
6	Enclosure System	Southwest Corner	Check for leaks in sloping curtain wall in SW corner of building	1	LS	\$ 1,000.00	\$ 1,000					\$ 1,	000	5 1,450
7	Enclosure System	Connector to Building CM	Add sill flashing to direct water away from brick	1	LS	\$110,000.00	\$ 110,000					\$ 110,	000 8	5 159,500
Finish S	ystem				1.0	<b>•</b> • • • • • • • •	<u> </u>			1		<u> </u>		
1	Finish System	General	Repair water damage to interior soffits	1	LS	\$ 2,500.00	\$ 2,500		ļ			\$2,	500 8	3,625
HVAC S	ystem	T							1	1		r		
1	H) (AC System	Puilding	Perform mechanical system retro-commissioning to restore the building mechanical	1	10			¢ 01 950 00	¢ 01.950			¢ 01		122 102
I	HVAC System	Building	report to identify notential operation issues	1	LO			φ 91,650.00	\$ 91,000			φ 91,	000 0	5 155,165
2	HVAC System	Roof	Replace HV/MUA units 1.2 &3	3	FA			\$ 9.075.00	\$ 27,225			\$ 27.	225	39,476
3	HVAC System	Roof	Replace exhaust fans EF-2 and EF-3.	2	EA			\$ 6.050.00	\$ 12.100			\$ 12.	100 5	5 17.545
4	HVAC System	Roof	Replace damaged powered unit.	1	EA			\$ 6,650.00	\$ 6,650			\$6.	650 \$	5 9,643
F		Devil dire e	Implementation of the recommendations that come out of the retro-commissioning	F4 000	05			¢ 1.00	¢ 74.504			ф <b>7</b> 4	504	102.040
5	HVAC System	Building	activates.	51,880	SF			\$ 1.38	\$ 71,594			<b>\$</b> 71,	594 3	5 103,812
6	HVAC System	Roof	Replace RTU 1, 2, and 3 with new RTU's with DX cooling and hot water heat	3	EA	\$ 3,000.00		\$ 70,000.00	\$ 210,000	\$ 3,000.00		\$ 210,	000	304,500
7	HVAC System	Mechanical Room and	Remove steam boiler and install electric heat in connector	1	LS			\$ 25,000.00	\$ 25,000			\$ 25,	000 3	36,250
D1 11		connector												
Plumbin	g System	1	Material and the state of the second						-	1	<b></b>	1	<u> </u>	
1	Plumbing System	Mechanical CK-148	Water heaters continue to have issues/problems and are always being fixed. Replace the	1	LS			\$ 18,150.00	\$ 18,150			\$ 18,	150 \$	26,318
Tempera	ature Controls		two water heaters with high enciency units.						1					
Tompore			Replace existing Desigo (Siemens) BAS controls with new Tridium (Honeywell) system							1		r		
1	Temperature Controls	Building	Replace pneumatic operation with electric. Calibrate devices, review sequences of	51,880	SF			\$ 10.00	\$ 518,800			\$ 518,	800 \$	5 752,260
		, , , , , , , , , , , , , , , , , , ,	operation, etc.including terminal box controlers	-										
Power S	ystems					-			-					
1	Power Systems	General	Several panels serving kitchen areas in the northwest part of the building were not	5	FA					\$ 5,000,00	\$ 25,000	\$ 25	000	36 250
•			replaced in 2005 and are due for replacement.	<u> </u>						¢ 0,000.00	÷ _0,000	ф <u> </u>		
2	Power Systems	Extorior	The medium-voltage S&C "PINH" pad-mount switch and 1000 kVA transformer are rusty	1	19					\$ 54 400 00	¢ 54.400	¢ 54	100 0	70 000
2	Fower Systems	Exterior	transformer.		L3					\$ 54,400.00	φ 54,400	φ 54,	400	70,000
			Electrical equipment had no indication of maintenance or testing since original installation		1.0					<b>* 7 5</b> 00 00	<b>* 7 5 0 0</b>	ф <b>т</b>	500	40.075
3	Power Systems	General	in 2005. Testing / maintenance is recommended at regular intervals.	1	LS					\$ 7,500.00	\$ 7,500	\$7,	500 \$	5 10,875
			Existing arc flash labels (where installed) are generic type and do not indicate incident											
4	Power Systems	General	energy boundaries, available fault current, etc While not required by code, it is	1	LS					\$ 4,000.00	\$ 4,000	\$4,	000 8	5,800
			In the Main Kitchen and the Demo Pastry Shon (CK-116), there are no apparent means for											
5	Power Systems	Kitchens	automatic shutoff for electrical devices under the hoods. These devices must be de-	3	FA					\$ 5,000,00	\$ 15,000	\$ 15	000	5 21,750
Ū			energized upon hood fire suppression activation.	Ũ	_, .					¢ 0,000.00	¢ .0,000	ф . <b>с</b> ,		
6	Power Systems	Men's Toilet CK-132	Two branch panels are located in Toilet Rooms, which is not permitted by the NEC. These	2	E۸					\$ 32,000,00	\$ 64.000	¢ 64	000	02 800
		Women's Toilet CK-131	panels should be moved. Includes \$20,000 for architectural repairs.	<u> </u>						ψ 02,000.00	ψ 04,000	ψ 04,		, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
7	Power Systems	General	Electrical revisions needed in support of HVAC equipment replacement.	51,880	SF					\$ 2.00	\$ 103,760	\$ 103,	760 \$	5 150,452
Lighting	System										•			
1	Lighting System	General	Lighting consists of fluorescent fixtures. Lighting should be replaced with LED.	51,880	SF					\$ 18.00	\$ 933,840	\$ 933,	840 \$	5 1,354,068
Code Sy	stems and Barrier Free								1	1		1	-	
1	Code Systems and Barrier Free	Northwest Kitchen	I oliet rooms are not accessible, including toilet stalls, lavatories and entry doors. They will require complete remodel. Accessible lockers and bonch should also be provided	1	LS	\$ 50,000.00	\$ 50,000					\$ 50,	000 \$	5 72,500
L							\$ 170 500		\$ 021 260		\$ 1 207 500	\$ 2.262	360 0	3 121 126
							ψ 173,300		ψ 301,303		ψ 1,207,300	ψ ∠,500,	000 0	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

# **BUILDING CL**



Use:	Classrooms, Office and Labs
------	-----------------------------

Year Built: 1982

Total Area: 30,400 SF

- Floors: 1
- 5 Year DMB: \$777,545
- CRV: \$16,476,800
- FCI: 4.72%

#### **COMMENTS**

#### **Roof System**

• JD Chandler roof installed in 2018.

#### Exterior

• Exterior brick needs to be tuck pointed and coping replaced with full copings.

#### **Finish System**

• Finishes updated.

#### **HVAC Systems**

• HVAC equipment, including controls, was replaced in 2018.

#### **Lighting System**

• Lighting and controls were upgraded in 2018 and are in good condition.



Existing Switchboard



## Building CL

Ne	Itom/Description	Location Notes		Otre	Linit	Archite	ectural	Mech	anical	Elec	trical	Constructio	n Draiget Cost
INO.	item/Description	Location	Notes	Qıy.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	Cost	Project Cost
Roof Sys	stem												
1	Roof System	Copings	Replace all copings with full width copings.	1	LS	\$ 15,000.00	\$ 15,000					\$ 15,00	0 \$ 21,750
Enclosu	re System												
1	Finish System	All Elevations	Clean and tuck point brick.	1	LS	\$ 12,000.00	\$ 12,000		\$ -		\$-	\$ 12,00	0 \$ 17,400
2	Finish System	All Windows	Caulk windows.	1	LS	\$ 3,000.00	\$ 3,000		\$ -		\$-	\$ 3,00	0 \$ 4,350
3	Finish System	East Elevation	Repair/ replace window mullions.	1	LS	\$ 3,000.00	\$ 3,000		\$ -		\$-	\$ 3,00	0 \$ 4,350
4	Finish System	Foundry	Replace lintel over foundry opening.	1	LS	\$ 3,000.00	\$ 3,000		\$ -		\$-	\$ 3,00	0 \$ 4,350
5	Finish System	East Elevation	Replace expansion joint in walkway.	1	LS	\$ 1,500.00	\$ 1,500		\$ -		\$-	\$ 1,50	0 \$ 2,175
Plumbin	g System												
1	Plumbing System	Boiler Room CL-116	Water heater and flue damaged from water and need to be replaced.	1	LS			\$ 4,275.00	\$ 4,275			\$ 4,27	5 \$ 6,199
Power S	ystems										-		
1	Power Systems	General	A majority of electrical distribution equipment is 41 years of age and is nearing end of expected useful life. Replacement is recommended in next major renovation.	30,400	SF					\$ 16.00	\$ 486,400	\$ 486,40	0 \$ 705,280
2	Power Systems	General	Existing arc flash labels are generic type and do not indicate incident energy boundaries, available fault current, etc While not required by code, it is recommended to update power system study and labeling to match that of building CA.	1	LS					\$ 8,000.00	\$ 8,000	\$ 8,00	0 \$ 11,600
							\$ 37,500		\$ 4,275		\$ 494,400	\$ 536,17	5 \$ 777,454

## **BUILDING CM**



Use:	Theater

- Year Built: 1982
- Total Area: 71,954 SF
- Floors: 2
- 5 Year DMB: \$4,310,157
- CRV: \$42,093,090
- FCI: 10.24%

#### **COMMENTS**

#### **Roof System**

• JD Chandler roof installed in 2012.

#### **Finish System**

• Finishes updated in 2018.

#### **HVAC Systems**

• HVAC systems, including controls, was replaced in 2018.

#### **Lighting System**

• Lighting and controls for theater and lobby areas should be replaced with new light fixtures and controls.



Existing Distribution Equipment





## Building CM

No	Itom/Description	Location	Notos	Otv	Linit	Archite	Architectural		Mechar	nical	Electrical		Const	truction	Draiget C	`oot
INO.	item/Description	Location	Notes	Qty.	Unit	Unit Cost	Subtotal	Unit Co	ost	Subtotal	Unit Cost	Subtotal	C	ost	Project Co	ost
Roof Sys	stem															
2	Roof System	Roof	Replace coping with a coping that goes down over the face of the brick.	1	LS	\$ 15,000.00	\$ 15,000						\$	15,000	\$ 21,	,750
3	Roof System	Roof	Inspect and repair roof at upper lobby.	1	LS	\$ 5,000.00	\$ 5,000						\$	5,000	<b>\$</b> 7,'	,250
Enclosu	re System															
2	Enclosure System	Windows	Add sill flashing at windows.	1	LS	\$ 5,000.00	\$ 5,000						\$	5,000	<b>\$</b> 7,	,250
3	Enclosure System	Throughout	Clean and tuck point brick where sill flashing added.	1	LS	\$150,000.00	\$ 150,000						\$ 1	150,000	\$ 217,	,500
Finish S	ystem							-			-					
1	Finish System	Lobby	Repair soffit on second level at south windows.	1	LS	\$ 2,500.00	\$ 2,500						\$	2,500	\$3,	,625
2	Finish System	Lobby	Repair soffit on second level at west entrance to seating.	1	LS	\$ 1,500.00	\$ 1,500						\$	1,500	\$2,	,175
3	Finish System	Back of House	All finishes need to be updated in back of house.	1	LS		\$-						\$	-	\$	-
4	Finish System	Lobby	All finishes need to be updated in lobby.	1	LS		\$-						\$	-	\$	-
5	Finish System	Seating	All finishes need to be updated in seating area.	1	LS		\$-						\$	-	\$	-
Fixed Ec	quipment															
1	Fixed Equipment	Auditorium	Orchestra platform lift equiopment is at the end of it's expected life.	1	LS	\$ 50,000.00	\$ 50,000						\$	50,000	\$ 72,	,500
2	Fixed Equipment	Scene Shon	Review mezzanine framing and supports for proper sizing - framing member size and	1	19	\$ 20,000,00	\$ 20,000						¢	20.000	\$ 20	000
			spacing appears inadequate.	1	20	φ 20,000.00	φ 20,000						Ψ	20,000	φ 23,0	
Plumbin	g System							-			-					
1	Plumbing System	Building	Portion of the domestic cold water distribution piping system are galvanized steel. Due to	600	LE			\$ 5	5.00	\$ 33,000			\$	33,000	\$ 47	850
			it's age the piping is showing signs of deterioration and should be replaced.					Ψ C		+ 00,000					÷,	
2	Plumbing System	Building	Portion of the cold and not water piping have missing and damaged insulation. The	71,954	SF			\$	0.77	\$ 55,405			\$	55,405	\$ 80,	,337
Tempera	ature Controls												<u> </u>			
rempere			Replace and upgrade controllers and control components for added efficiency and					Γ.	Т		1		<b>T</b>	<b>—</b>		_
1	Temperature Controls	Building	enhanced maintenance functions.	71,954	SF			\$	4.83	\$ 347,538			\$ 3	347,538	\$ 503,9	,930
Power S	ystems	-														
1	Dower Systems	Conorol	A majority of electrical distribution equipment is 41 years of age and is nearing end of	71 054	SE.						¢ 20.00	¢ 1 120 090	¢ 1/	120.090	¢ 2,006	666
-	Fower Systems	General	expected useful life. Replacement is recommended in next major renovation.	71,904	ЪГ						φ 20.00	ъ 1,439,060	φ 1,4	+39,000	φ 2,000,0	000
			Existing arc flash labels are generic type and do not indicate incident energy boundaries,												<b>.</b>	
2	Power Systems	General	available fault current, etc While not required by code, it is recommended to update	1	LS						\$ 8,000.00	\$ 8,000	\$	8,000	\$ 11,6	600
			power system study and labeling to match that of building CA.										╂───			
			plugged into a receptacle (not equipped with an in-use cover) installed in the exterior wall													
3	Power Systems	Roof	at grade. It is recommended to add GFCI receptacles provided with weatherproof, in-use	4	EA						\$ 1,500.00	\$ 6,000	\$	6,000	\$ 8,	,700
			covers on the roof.													
			Cored openings (approximately 24" above grade) where conduits/LB fittings are leaving										1			
4	Power Systems	Exterior (East Facing Wall)	the building are not sealed. A draft was noticed through these openings in the brick	2	EA						\$ 500.00	\$ 1,000	\$	1,000	\$ 1, <sup>,</sup>	,450
			exterior. These openings should be properly sealed.													
		Catualy Above Theater	Lable routed through catwalk access door opening (appears to be a coax cable for													
5	Power Systems	(Stage Left)	on theatrical needs is recommended (cost assumes (1) 2" sleeve at each catwalk door	4	EA						\$ 500.00	\$ 2,000	\$	2,000	\$ 2,	,900
			above theatre)													
L											8					

## Building CM

No	Itom/Description	Logation	Netoo	Otre	Linit	Archite	ctural	Mech	anical	Elec	trical	Construction	Draiget Cost
NO.	item/Description	Location	Notes	Qiy.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	Cost	Project Cost
Lighting	ng System												
1	Lighting System	Theater and Lobby	The lighting within the Theater and Lobby consists of multiple types of non-LED fixtures. Lighting within the Lobby (approximately 12,500sqft) should be replaced with LED and new controls to meet the current ASHRAE requirements. Back of house corridors, restrooms, green room, and offices areas have already been updated to LED as part of a 2018 renovation to buildings CL and CM.	12,500	SF					\$ 65.00	\$ 812,500	\$ 812,500	\$ 1,178,125
Code Sy	vstems and Barrier Free												
1	Code Systems and Barrier Free	General	Lobby railings are not graspable	1	LS	\$ 8,500.00	\$ 8,500					\$ 8,500	\$ 12,325
2	Code Systems and Barrier Free	General	Seating railings are not graspable and landings are not adequate	1	LS	\$ 2,500.00	\$ 2,500					\$ 2,500	\$ 3,625
3	Code Systems and Barrier Free	General	Barrier free seating not dispersed	1	LS	\$ 3,000.00	\$ 3,000					\$ 3,000	\$ 4,350
4	Code Systems and Barrier Free	General	Barrier free stalls are not up to date	1	LS	\$ 5,000.00	\$ 5,000					\$ 5,000	\$ 7,250
				-			\$ 268,000		\$ 435,942		\$ 2,268,580	\$ 2,972,522	\$ 4,310,157

# **BUILDING CN**



Use:	Classrooms and Offices
Year Built:	1996, 2017 Renovation
Total Area:	65,357 SF
Floors:	2
5 Year DMB:	\$1,535,920
CRV:	\$26,208,157

FCI: 5.86%

#### **COMMENTS**

#### **Roof System**

- JD Chandler roof installed in 2017.
- Roof warranty expired in 2021.

#### **HVAC System**

- New chiller buffer tank provided to reduce cycling of chiller in Summer 2017.
- Air handling units, boilers and pumps were replaced in Summer 2017.

#### **Temperature Controls**

• Temperature controls were upgraded in Summer 2017.

#### Lighting System

• Lighting and controls were upgraded in 2017 and are in good condition.





## Building CN

No	Itom/Decorintion	Location	Netoo	054	Linit	Archite	ectural	Mecha	anical	Elec	Electrical		struction	Draiget Co	
INO.	lien/Description	Location	Notes	Qıy.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal		Cost	Projec	i Cosi
Enclosu	re System														
1	Enclosure System	Substation	Install sweep at substation doors to exterior.	1	LS	\$ 500.00	\$ 500					\$	500	\$	725
2	Enclosure System	Exterior	Re-caulk windows - exterior.	1	LS	\$ 10,000.00	\$ 10,000					\$	10,000	\$	14,500
3	Enclosure System	Substation	Repair or replace exterior door frame to substation room.	1	LS	\$ 3,000.00	\$ 3,000					\$	3,000	\$	4,350
Finish Sy	vstem														
1	Finish System	Interior	Re-caulk windows.	1	LS	\$ 5,000.00	\$ 5,000					\$	5,000	\$	7,250
Power S	ystems	-													
1	Power Systems	Main Electrical Room	A majority of electrical distribution equipment is 26 years of age and is nearing end of expected useful life. Replacement is recommended in next major renovation.	65,357	SF					\$ 15.00	\$ 980,355	\$	980,355	\$ 1,4	21,515
2	Power Systems	General	Existing arc flash labels are generic type and do not indicate incident energy boundaries, available fault current, etc While not required by code, it is recommended to update power system study and labeling to match that of building CA.	1	LS					\$ 8,000.00	\$ 8,000	\$	8,000	\$	11,600
3	Power Systems	Roof	It appears the existing lightning protection system was removed from the roof as part of a previous renovation. Air terminals were noticed to be remaining on some mechanical HVAC equipment. The lightning protection should be removed in its entireity. A partially installed lightning protection system can negatively impact the possible damage caused by a lightning strike.	5	EA					\$ 200.00	\$ 1,000	\$	1,000	\$	1,450
4	Power Systems	IDF Closet N234	Ceiling smoke detector is not secure to its box and is hanging by wires. This smoke detector should be inspected for damage and properly fastened to the box.	1	LS					\$ 100.00	\$ 100	\$	100	\$	145
5	Power Systems	Electrical N132	RP-1B is installed behind the door swing, which is not permitted by the NEC. The door should be revised to swing out of the room.	1	LS					\$ 20,000.00	\$ 20,000	\$	20,000	\$	29,000
6	Power Systems	Electrical N232	RP-2B is installed behind the door swing, which is not permitted by the NEC. The door should be revised to swing out of the room.	1	LS					\$ 20,000.00	\$ 20,000	\$	20,000	\$	29,000
7	Power Systems	Data Center Office N254	Coverplate is missing from the light switch, exposing the wiring behind the device. A cover plate should be installed.	1	LS					\$ 100.00	\$ 100	\$	100	\$	145
8	Power Systems	General	It was noticed in IDF closets that the floor/ceiling cores were not sealed around the passing cables. These should be sealed to maintain fire rating.	8	EA					\$ 300.00	\$ 2,400	\$	2,400	\$	3,480
Code Sy	stems and Barrier Free														
1	Code Systems and Barrier Free	Stairs	Provide cane rail under stairs in lobby.	2	EA	\$ 1,500.00	\$ 3,000					\$	3,000	\$	4,350
2	Code Systems and Barrier Free	Toilet Rooms	provide pipe protection at toilet room sinks.	24	EA	\$ 200.00	\$ 4,800					\$	4,800	\$	6,960
3	Code Systems and Barrier Free	Technology Closets	Seal penetrations in floor in tech closets.	1	LS	\$ 1,000.00	\$ 1,000					\$	1,000	\$	1,450
							\$ 27,300		\$ -		\$ 1,031,955	<b>\$</b> 1,	059,255	\$ 1,5	35,920

# **BUILDING CP**



Use:	Food Service, Conference and Bookstore
Year Built:	2004
Total Area:	34,496 SF
Floors:	1
5 Year DMB:	\$2,160,874
CRV:	\$14,281,344
FCI:	15.13%

#### **COMMENTS**

#### **Roof System**

- Single-ply roof installed in 2004.
- Roof warranty expired in 2019.

#### **HVAC Systems**

- Existing air-cooled chiller and pumps have exceeded their useful life and should be replaced.
- Existing boilers and pumps have exceeded their useful life and should be replaced.

#### **Temperature Controls**

• Replace existing Desigo (Siemens) BAS controls with new Tridium (Honeywell) system.

#### **Power Systems**

• Most electrical equipment was upgraded in 2004 and that equipment is generally in good condition.

#### Lighting System

• Exit signs are LED.

BUILDING "CP" 100 LEVEL







### Building CP

No. Item/Description		Lesstian	Notes Qty.	0.5	Linit	Archite	ectural	Mech	Mechanical		Electrical		Con	struction	Duei	last Cast
INO.	liem/Description	Location	Notes	Qty.	Unit	Unit Cost	Subtotal	Unit Cost	S	ubtotal	Unit Cost	Subtotal		Cost	Proj	ect Cost
Roof Sys	stem															
1	Roof System	Roof	Tapered insulation around drains holds water.	1	LS	\$ 8,000.00	\$ 8,000						\$	8,000	\$	11,600
Enclosu	re System															
1	Enclosure System	Exterior	Recaulk control joints in brick.	1	LS	\$ 5,000.00	\$ 5,000	Ī					\$	5,000	\$	7,250
2	Enclosure System	South Entrance	Replace damaged metal wall panels at south entrance.	1	LS	\$ 1,000.00	\$ 1,000						\$	1,000	\$	1,450
3	Enclosure System	South Elevation	Recaulk windows on south elevation.	1	LS	\$ 2,000.00	\$ 2,000						\$	2,000	\$	2,900
4	Enclosure System	North Entrance	Clean transleucent panels at north entrance.	1	LS	\$ 1,000.00	\$ 1,000						\$	1,000	\$	1,450
5	Enclosure System	Throughout	Add sill flashing at curtainwall.	1	LS	\$ 5,000.00	\$ 5,000						\$	5,000	\$	7,250
Finish Sy	ystem															
1	Finish System	South Entrance	Repair gypsum board soffit at south entrance.	1	LS	\$ 1,500.00	\$ 1,500						\$	1,500	\$	2,175
HVAC Sy	vstem	-	• • •													
			Perform mechanical system retro-commissioning to restore the building mechanical					-						·		
1	HVAC System	Building	system back to the original design intent and complete an air and water system balance report to identify potential operation issues	1	LS			\$ 71,610.00	\$	71,610			\$	71,610	\$	103,835
2	HVAC System	Building	Implementation of the recommendations that come out of retro commissioning activities	34,496	SF			\$ 1.38	\$	47,604			\$	47,604	\$	69,026
2	HVAC System	Mechanical Room	Replace air cooled chiller and pumps	1	LS			\$ 300,000.00	\$	300,000			\$	300,000	\$	435,000
2	HVAC System	Chiller Yard	Replace gas fired boilers and pumps	1	LS			\$ 210,000.00	\$	210,000			\$	210,000	\$	304,500
Tempera	ture Controls							<u> </u>		,	•					· ·
			Replace existing Desigo (Siemens) BAS controls with new Tridiuum (Honeywell) system.						[				1		1	
1	Temperature Controls	Building	Commission controls, replace pneumatic operation with electric. Calibrate devices, review	34,496	SF			\$ 4.83	\$	166,616			\$	166,616	\$	241,593
			sequences of operation, etc.													
Power S	ystems							-					_		_	
1	Power Systems		RP-5 is installed behind the door swing, which is not permitted by the NEC. This panel	1	IS						\$ 32,000,00 \$	32 000	\$	32 000	\$	46 400
· ·		Kitchen Servery	should be moved. Includes \$20,000 for architectural repairs.								+ 0 <u></u> ,000.00 +	01,000	Ť	0_,000	Ť	
2	Dower Systems		Existing arc flash labels are generic type and do not indicate incident energy boundaries,	1	1.0						¢ 000.00 ¢	0 000	¢	9 000	¢	11 600
2	Power Systems	General	available fault current, etc while not required by code, it is recommended to update	1	LS						\$ 0,000.00 \$	0,000	Ф	0,000	Ф	11,000
		General	Electrical equipment had no indication of maintenance or testing since original installation										1.			
3	Power Systems	General	in 2004. Testing / maintenance is recommended at regular intervals.	1	LS						\$ 10,000.00 \$	10,000	\$	10,000	\$	14,500
Lighting	System									<b>.</b>						
	• • • • • • • • • • • • • • • • • • •		Existing lighting is fluorescent & current controls are not fully code compliant with latest						[				T		1	
1	Lighting System	General	energy codes. Recommended to replace with LED and controls as a part of the next major building renovation.	34,496	SF						\$ 18.00 \$	620,928	\$	620,928	\$	900,346
							\$ 23,500	-	\$	795,830	\$	670,928	\$ 1	1,490,258	\$ 2	2,160,874

# **BUILDING CR**



Use:Classrooms, Offices and LabsYear Built:2007Total Area:36,478 SFFloors:25 Year DMB:\$1,978,133CRV:\$16,415,100

FCI: 12.05%

#### **COMMENTS**

#### **Roof System**

• Bondcote single-ply roof installed in 2008. Roof should be scheduled for replacement.

#### **Temperature Controls**

• Replace existing Desigo (Siemens) BAS controls with new Tridium (Honeywell) system.

BUILDING "R" 100 LEVEL

NORTH



BUILDING "R" 200 LEVEL

NORTH



## Building CR

No	Item/Description	Location	Notes	Qty.	Unit	Architectural		Mec	Mechanical		Electrical		n <sub>Dro</sub>	Draiget Coat	
NO.						Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	Cost	FIU	Jeci Cosi	
Enclosure	System														
1 Er	nclosure System	General	Recaulk control joints in brick.	1	LS	\$ 5,000.00	\$ 5,00	0				\$ 5,00	0 \$	7,250	
2 Er	nclosure System	General	Recaulk louvers.	1	LS	\$ 2,000.00	\$ 2,00	C				\$ 2,00	0 \$	2,900	
2 Er	nclosure System	Roof	Replace roof	18,240	SF	\$ 14.00	\$ 255,36	C				\$ 255,36	60 \$	370,272	
Finish Syst	tem														
1 Fir	nish System	Main Entrance Lobby	Repair gypsum ceiling at main entry.	1	LS	\$ 1,500.00	\$ 1,5	0				\$ 1,50	0 \$	2,175	
HVAC Syst	em														
			Perform mechanical system retro-commissioning to restore the building mechanical												
1 H\	VAC System	Building	system back to the original design intent and complete an air and water system balance	1	LS			\$ 76,780.00	\$ 76,780			\$ 76,78	<b>0</b> \$	111,331	
<u> </u>			report to identify potential operation issues.												
2 H\	VAC System	Building	Implementation of the recommendations that come out of retro commissioning activities	36,478	SF			\$ 1.38	\$ 50,340			\$ 50,34	0\$	72,992	
Temperatur	re Controls								•	<b>1</b>					
		5	Replace existing Desigo (Siemens) BAS controls with new Tridium (Honeywell) system.		05			<b>•</b> • • • • •				<b>•</b> • • • • <b>•</b>			
1 Ie	emperature Controls	Building	Commission controls, replace pneumatic operation with electric. Calibrate devices, review	36,478	SF			\$ 10.00	\$ 364,780			\$ 364,78	\$0 \$	528,931	
Power Syst	toms		sequences of operation, etc. including terminal box controlers												
			A majority of electrical equipment was missing arc flash labels. It is recommended to						1	1	[	1	1		
1 Pc	ower Systems	General	provide a power system study and labeling.	1	LS					\$ 15,000.00	\$ 15,000	\$ 15,00	0 \$	21,750	
	awar Svatama	Conorol	Per existing labels, testing and maintenance has not been performed on electrical	1	10					¢ 20.000.00	¢ 20.000	¢ 20.00		20.000	
2 F0	Jwei Systems	General	equipment since 2013.	1	L3					\$ 20,000.00	\$ 20,000	φ 20,00	φ	29,000	
3 Pc	ower Systems	General	Outdoor receptacles do not have in-use covers	1	LS					\$ 3,000.00	\$ 3,000	\$ 3,00	0 \$	4,350	
Lighting Sy	ystem							<u>_</u>		_		_			
1 Liv	ahtina System		l ighting in elec / mech spaces cannot incorporate auto-off controls. Replace local controls	1	IS					\$ 300.00	\$ 300	\$ 30	0 \$	435	
	gg. 2,0.0	General		•				_		+	+	+	• •		
2 Lic	ghting System	Conoral	Existing lighting is fluorescent & current controls are not code compliant. Recommended to	36,478	SF					\$ 15.00	\$ 547,170	\$ 547,17	0 \$	793,397	
		General	Central inverter unit for emergency lighting did not have operable indicator lights. It is												
3 Lie	Lighting System		unclear if unit is working properly. Recommend repair or replacement of inverter unit. Cost	1	IS					\$ 20,000,00	\$ 20,000	\$ 20.00	0 \$	29 000	
U Lig		General	shown represents replacement.	•	20					φ 20,000.00	φ 20,000	φ 20,00	Ψ	20,000	
Code Syste	Code Systems and Barrier Free														
1 Cr	ode Systems and Barrier Free	General	Install can rail under stairs.	2	EA	\$ 1,500.00	\$ 3.00	D				\$ 3.00	0 \$	4,350	
							\$ 266.86	0	\$ 491,900		\$ 605,470	\$ 1,364.23	0 \$	1,978,133	

## **BUILDING CS**



Use:	Offices and Unassigned
------	------------------------

- Year Built: 1988
- Total Area: 42,055
- Floors: 4
- 5 Year DMB: \$2,571,506 CRV: \$17,663,100
- FCI: 14.56%

#### **COMMENTS**

#### **Roof System**

• Roof installed in 2005. Roof should be scheduled for replacement.

#### **HVAC Systems**

• Existing rooftop HVAC units (2) serving building have exceeded their useful life and should be replaced.

#### Lighting System

• Insufficient lighting (normal and emergency) at upper level. Included in lighting replacement cost in item 1 above.
"CS" BUILDING 100 LEVEL

NORT



# "CS" BUILDING 200 LEVEL



"CS" BUILDING 300 LEVEL

NORTH



# "CS" BUILDING 400 LEVEL



## Building CS

Ne	Itom/Deparintion	Location	Notos	Otr	Linit	nit		Mech	Mechanical		Electrical		Construction		at Cast
INO.	nem/Description	Location	Notes	Qiy.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	(	Cost	Projec	iojeci Cosi
Roof Sys	stem														
1	Roof System	Building	Provide overflow drains/ scuppers.	3	EA	\$ 2,000.00	\$ 6,000					\$	6,000	\$	8,700
2	Roof System	Canopies	Rework downspouts to not drain onto sidewalk.	1	LS	\$ 1,500.00	\$ 1,500					\$	1,500	\$	2,175
3	Roof System	Roof	Replace roof	10514	SF	\$ 14.00	\$ 147,196					\$	147,196	\$2	213,434
Enclosu	re System														
1	Enclosure System	North and West Elevations	Repair wall at grade below windows on north and west elevations.	1	LS	\$ 8,000.00	\$ 8,000					\$	8,000	\$	11,600
2	Enclosure System	Throughout	Clean metal panels.	1	LS	\$ 10,000.00	\$ 10,000					\$	10,000	\$	14,500
Finish S	ystem														
1	Finish System	Lobby	Repair vinyl wall finish in lobby - all levels.	1	LS	\$ 2,500.00	\$ 2,500					\$	2,500	\$	3,625
HVAC S	/stem			-	-			-		-					
1	HVAC System	Boiler Room 445	The boiler room is not ventilated to remove the heat generated by the boilers.	1	LS			\$ 18,150.00	\$ 18,150			\$	18,150	\$	26,318
2	HVAC System	Building	The piping system is not completely labels. Label the piping.	42,055	SF			\$ 0.15	\$ 6,308			\$	6,308	\$	9,147
3	HVAC System	Roof	Repalce two RTU's with new.	2	EA	\$ 3,000.00	\$ 6,000	\$ 190,000.00	\$ 380,000	\$ 3,000.00	\$ 6,000	\$	392,000	\$5	568,400
Plumbin	g System														
1	Dlumbing System	Puilding	Portion of the domestic cold water distribution piping are galvanized steel. Due to it's age	100	1.5			¢ 55.00	¢ 5,500			¢	5 500	¢	7 075
1		Building	the piping is showing signs of deterioration and should be replaced.	100	LF			\$ 55.00	φ <u>5,500</u>			Φ	5,500	φ	7,975
2	Plumbing System	Building	Portion of the cold and hot water piping have missing and damages insulation. The insulation should be replaced.	42,055	SF			\$ 0.06	\$ 2,523			\$	2,523	\$	3,659
Tempera	ture Controls														
			Update and commission controls, replace pneumatic operation with electric. Calibrate												
1	Temperature Controls	Building	devices, review sequences of operation, etc. Provide battery backup on central	42,055	SF			\$ 10.00	\$ 420,550			\$	420,550	\$ 6	09,798ئ
			temperature controls panel.									L			
Power S	ystems			T.	1	<b>I</b> 1		r	-	1	-				
1	Dowor Systems	Conorol	Existing arc flash labels are generic type and do not indicate incident energy boundaries,	1	10					¢ 15 000 00	¢ 15.000	¢	15 000	¢	21 750
I	Power Systems	General	nower system study and labeling		LS					\$ 15,000.00	φ 15,000	Φ	15,000	φ	21,750
-			No signs of electrical equipment maintenance or testing. Given the age of the existing								<b>.</b>			•	
2	Power Systems	General	equipment, electrical testing is recommended.	1	LS					\$ 20,000.00	\$ 20,000	\$	20,000	\$	29,000
з	Power Systems	Boof	Existing natural gas generator is 18 years old and is approaching end of useful expected	1	E۸					\$ 70,000,00	\$ 70.000	¢	70.000	¢ 1	101 500
		1,001	life. Recommend replacement within next 2-5 years.							\$ 70,000.00	φ 70,000	Ψ	70,000	ψι	01,500
Lighting	System			-		-									
			Majority of existing lighting is fluorescent & current controls are not code compliant.												
1	Lighting System	General	Recommended to replace with LED and controls as a part of the next major building	42,055	SF					\$ 15.00	\$ 630,825	\$	630,825	\$9	14,696
Codo Su	atoms and Parrier Free			1	I					1		L			
	Stenis and Darrier Free	Toilot Booma		4	10	¢ 15.000.00	¢ 45.000	1		1		¢	15.000	¢	21 750
	Code Systems and Parrier Free		Damer Free water closets are not current code complient.	10		¢ 10,000.00	φ 10,000 ¢ 0,400			1		φ φ	2 400	φ Φ	2 4 9 0
2	Coue Systems and Barrier Free	I Oliet Rooms	וווזימוו אוף איטובטווטוו אבוטיא ומימנטוובי מווע זוווגיג.	12	EA		→ 2,400		<b>*</b>		<b>*</b> 744.005		2,400	۵ ۵	3,480
							<b>\$</b> 198,596		ə 833,032		\$	<b>\$</b> 1,	,773,453	\$2,5	<i>x</i> 7,506



Use:	Classrooms,	Conference	and	Offices
000.	014001001110,	001110101100	ana	0111000

Year Built: 1991

Total Area: 88,768 SF

Floors: 2

5 Year DMB: \$5,134,806

CRV: \$37,016,256

FCI: 13.87%

## **COMMENTS**

## **Roof System**

- Firestone EPDM roof installed in 2014.
- Roof warranty expires in 2029.

## **Roof System (Addition)**

- Firestone EPDM roof installed in 2019.
- Roof warranty expires in 2034.

## **HVAC System**

- Air handling units, boilers and pumps replaced summer 2014.
- Two original Mammoth rooftop air handling units (DX cooling with gas heat) are currently in design stage of replacement. Associated replacement costs are not included within this report but called out for informational purposes (\$750,800).
- Cooling towers replacement is currently in design phase. Estimated replacement cost is indicated for informational purposes (\$194,000).

## **Temperature Controls**

• Building is served by both Tridium (Honeywell) and Continuum (Andover) controls. Remove the Andover portion and replace with Tridium.



Existing Substation





No	Itom/Description	Location	Notos	Otv	Linit	Archit	ectural			Mechanical			Electrical		Con	struction	Droid	act Cost
INO.	Item/Description	Location	Noles	Qiy.	Unit	Unit Cost	Su	btotal	Unit C	Cost	Subtotal	Unit Co	st	Subtotal	Cost		Proje	eci Cosi
Enclosur	e System																	
1	Enclosure System	Southwest Elevation	Recaulk control joints in granite base at Hall/ Dining.	1	LS	\$ 2,000.00	\$	2,000							\$	2,000	\$	2,900
2	Enclosure System	Southwest Elevation	Seal gaps in soffit at Hall/ Dining.	1	LS	\$ 1,500.00	\$	1,500							\$	1,500	\$	2,175
3	Enclosure System	East Elevation	Repair soffit at South entrance - east elevation.	1	LS	\$ 1,500.00	\$	1,500							\$	1,500	\$	2,175
4	Enclosure System	Throughout	Recaulk control joints in brick.	1	LS	\$ 7,000.00	\$	7,000							\$	7,000	\$	10,150
5	Enclosure System	Throughout	Clean limestone.	1	LS		\$	-							\$	-	\$	-
Finish Sy	rstem	•																
1	Finish System	General	Refinish soffit at entry vestibule in Lobby.	1	LS	\$ 1,000.00	\$	1,000							\$	1,000	\$	1,450
2	Finish System	General	Refinish floor in Mechanical Room UC 129.	1	LS	\$ 5,000.00	\$	5,000							\$	5,000	\$	7,250
3	Finish System	General	Refinish perimeter soffit at Hall/ Dining UC 142.	1	LS	\$ 3,000.00	\$	3,000							\$	3,000	\$	4,350
4	Finish System	General	Recaulk windows in East facing offices on second floor.	9	EA	\$ 150.00	\$	1,350							\$	1,350	\$	1,958
Plumbing	a System							· .										
			Portion of the domestic cold water distribution piping are galvanized steel. Due to it's age				1						<u> </u>		Ι.		Ι.	
1	Plumbing System	Building	the piping is showing signs of deterioration and should be replaced.	600	SF				\$	55.00	\$ 33,00	0			\$	33,000	\$	47,850
2	Dlumbing System	Building	Portion of the cold and hot water piping have missing and damages insulation. The	00 700	ог				¢	0.77	¢ 60.20	1			¢	60.251	¢	00 100
2	Plumbing System	Building	insulation should be replaced.	00,700	ЭГ				φ	0.77	<b>৯ 00,</b> 30				Ф	00,351	Ф	99,109
3	Plumbing System	Building	Replace domestic gas fired water heaters.	3	EA				\$ 2,0	00.00	\$ 6,00	00			\$	6,000	\$	8,700
Tempera	ture Controls																	
1	Temperatura Captrola	Puilding	Building is served by both Tridium (Honeywell) and Continuum (Andover) controls.	44 000	SE				¢	10.00	¢ 110.00	0			¢	440.000	¢	620 000
		Building	Remove the Andover portion and replace with Tridium (50% assumed).	44,000	эг				φ	10.00	ə 440,00	0			φ	440,000	φ	030,000
Power Sy	vstems							_				_			_		_	
1	Power Systems	General	A majority of electrical distribution equipment is 30 years of age and is nearing end of	88 768	SE							\$ 1	3 00 1	1 597 824	\$ 1	597 824	\$ 2	316 845
			expected useful life. Replacement is recommended in next major renovation.	00,700	01							Ψ 1	<u>,</u>	,007,024	Ψı	,007,024	ΨΖ	,010,040
			As an alternative to item 1 above, building-wide electrical testing and maintenance is									<b>*</b> • • • • •			<u>^</u>	00.000	•	40.000
2	Power Systems	General	recommended to identify potential issues with any older equipment. Labeling indicates	1	LS							\$ 28,00	1.00 8	\$ 28,000	\$	28,000	\$	40,600
┣───╋			Every and maintenance has not been performed since 2015.										$\rightarrow$					
3	Power Systems	UC1-123 Projection Room	alarm status at time of site visit. Testing / maintenance is recommended at regular	1	IS							\$ 1.00	0.00	5 1.000	\$	1.000	\$	1,450
			intervals.									<b></b>		.,	Ŧ	.,	Ť	.,
			Existing arc flash labels are generic type and do not indicate incident energy boundaries,															
4	Power Systems	General	available fault current, etc While not required by code, it is recommended to update	1	LS							\$ 8,00	).00 🗧	\$ 8,000	\$	8,000	\$	11,600
			power system study and labeling to match that of Building CA.															
			It appears the existing lightning protection system was removed from the roof as part of a															
_	Deverse Orietanes	Deef	previous renovation. Air terminals were noticed to be remaining on some portions of the	-								¢ 00		4 000	¢	4 000	¢	4 450
5	Power Systems	Rool	root and HVAC equipment. The lightning protection should be removed in its entireity. A	Э	EA							\$ 20	1.00	§ 1,000	Ф	1,000	\$	1,450
			caused by a lightning strike															
l iahtina	System						1								I			
			Lighting and controls were upgraded in 2014 with LED downlights and new fluorescent	r – –			T	- I				T	$-\tau$		Г		1	
1	Lighting System	General	lamps in general lighting fixtures. Within the next renovation, new LED lighting and controls	88,768	SF							\$ 1	5.00	5 1,331,520	\$ 1	.331,520	\$ 1.	,930,704
			should be included to meet current Ashrae standards.	,								,		, ,		, ,		, -
2	Lighting System	LIC1 125 Study Area	Light switch in this space was audibly arcing when operated. Light switches indicating this	1	19							¢ 20		000	¢	200	¢	200
		oon-125 Sludy Alea	level of deterioration should be replaced as soon as possible.	I	10							φ 20	·	¢ 200	φ	200	φ	290
Code Sys	stems and Barrier Free																	
1	Code Systems and Barrier Free	Lobby	Install cane rail at underside of stairs in Lobby	2	EA	\$ 1,500.00	\$	3,000							\$	3,000	\$	4,350
2	Code Systems and Barrier Free	Second Floor	Seal floor penetrations in IDF/ IT closets	1	LS	\$ 1,000.00	\$	1,000							\$	1,000	\$	1,450
							\$	26,350			\$ 547,35	1	-	\$ 2,967,544	\$ 3	,541,245	\$5	,134,806



056.	

- Year Built: 1999
- Total Area: 52,290 SF
- Floors: 2
- 5 Year DMB: \$6,745,226 CRV: \$23,394,310
- FCI: 28.83%

## **COMMENTS**

## **Roof System**

• Single-ply roof installed in 1999. Roof warranty expired in 2014. Roof should be scheduled for replacement.

## **Connector Bridge**

• Bridge enclosure system, including roof, windows and panels, leaks and should be replaced.

## **HVAC Systems**

Building HVAC systems should be retro-commissioned.

## **Temperature Controls**

• Building is served by both Tridium (Honeywell) and Desigo (Siemens) controls. Remove the Desigo portion and replace with Tridium.



Existing Substation





NIa	Itom/Docenintien		Netza	0.5	1.1	Architectural		Mecha	anical	Elec	lectrical		struction	Drainet Cast
INO.	item/Description	Location	INOTES	Qty.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	¢	Cost	Project Cost
Roof Sys	stem		•	-										
1	Roof System	Above Lobby	Re-seal Kal wall system.	1	LS	\$ 1,500.00	\$ 1,500					\$	1,500	\$ 2,175
2	Roof System	Roof	Re-paint gas piping.	1	LS	\$ 1,000.00	\$ 1,000					\$	1,000	\$ 1,450
2	Roof System	Roof	Repaice roof	26645	SF	\$ 14.00	\$ 373,030					\$	373,030	\$ 540,894
Enclosu	re System													
1	Enclosure System	Electrical Room	Replace door frame at electrical room.	1	LS	\$ 2,500.00	\$ 2,500					\$	2,500	\$ 3,625
2	Enclosure System	Bridge	Replace exterior finishes including roof and windows.	1	LS	\$240,000.00	\$ 240,000					\$	240,000	\$ 348,000
3	Enclosure System	Mechanical Louvers	Clean stained limestone at mechancial louvers.	1	LS	\$ 1,000.00	\$ 1,000					\$	1,000	\$ 1,450
Finish S	ystem													
1	Finish System	Office Suite 136	Repair vinyl wall covering.	1	LS	\$ 500.00	\$ 500					\$	500	\$ 725
HVAC S	ystem			•	<u> </u>									
			Perform mechanical system retro-commissioning to restore the building mechanical									Ī		
1	HVAC System	Building	system back to the original design intent and complete an air and water system balance	1	LS			\$ 89,980.00	\$ 89,980			\$	89,980	\$ 130,471
			report to identify potential operation issues.											
2	HVAC System	Building	Implementation of the recommendations that come out of retro-commissioning activities.	53,290	SF			\$ 30.00	\$ 1,598,700			\$1,	,598,700	\$ 2,318,115
Tempera	ture Controls													
			Building is served by both Tridium (Honeywell) and Desigo (Siemens) controls. Remove											
1	Temperature Controls	Building	the Desigo portion and replace with Tridium. Commission conrols, replace pneumatic	53,290	SF			\$ 10.00	\$ 532,900			\$	532,900	\$ 772,705
_			operation with electric, calibrate devices, review sequences of operation, etc.									<u> </u>		
Power S	ystems				· · · · · ·				1					
1	Power Systems	General	A majority of electrical distribution equipment is 23 years of age and is nearing end of	53,290	SF					\$ 18.00	\$ 959,220	\$	959,220	\$ 1,390,869
			expected useful life. Replacement is recommended in next major renovation.	-										
2	Power Systems	General	recommended to identify notential issues with any older equipment 1 abeling indicates	1	1.5					\$ 28,000,00	\$ 28,000	\$	28 000	\$ 40.600
2		General	testing and maintenance has not been performed since 2013.		10					φ 20,000.00	φ 20,000	Ψ	20,000	φ -0,000
			A majority of electrical equipment was missing arc flash labels. It is recommended to							<b>*</b> 04 000 00	<b>*</b> 04 000		04.000	
3	Power Systems	General	provide a power system study and labeling.	1	LS					\$ 21,000.00	\$ 21,000	\$	21,000	\$ 30,450
Lighting	System			-										
			Existing lighting is fluorescent and current controls are not fully code compliant with latest											
1	Lighting System	General	energy codes. Recommended to replace with LED and controls as a part of the next major	53,290	SF					\$ 15.00	\$ 799,350	\$	799,350	\$ 1,159,058
			building renovation. Includes 'UC connector' square footage.											
Code Sy	stems and Barrier Free			-						-				
1	Code Systems and Barrier Free	General	Install pipe protection below lavatories and sinks.	16	EA	\$ 200.00	\$ 3,200		\$-		\$-	\$	3,200	\$ 4,640
							\$ 622,730		\$ 2,221,580		\$ 1,807,570	\$4,	,651,880	\$ 6,745,226



Use:Classrooms and LabYear Built:2007Total Area:36,718Floors:25 Year DMB:\$1,777,048CRV:\$16,816,844FCI:10.57%

#### **COMMENTS**

## **Roof System**

• Duro-Last single-ply roof installed in 2007. Roof warranty expired in 2022. Roof should be scheduled for replacement.

## **Temperature Controls**

• Building Siemens Desigo controls should be upgraded to Tridium.









No	Item/Description	Location	Neteo	Otv	Unit	Architec	tural	Mecha	anical	Elec	trical	Constructio	Droject Con
INO.	item/Description	Location	Notes	Qty.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	Cost	Project Cos
Roof Sys	stem												
1	Roof System	Roof	Repair roof leak at main entry.	1	LS	\$ 3,000.00	3,000					\$ 3,00	0 \$ 4,35
2	Roof System	Roof	Re-paint gas piping.	1	LS	\$ 1,000.00	6 1,000					\$ 1,00	0 \$ 1,45
3	Roof System	Roof	Repalce roof	18400	SF	\$ 14.00	5 257,600					\$ 257,60	0 \$ 373,52
Enclosu	re System												
1	Enclosure System	Several Locations	Missing or loose mullion caps.	1	LS	\$ 1,500.00	5 1,500					\$ 1,50	0 \$ 2,17
2	Enclosure System	Throughout	Reseal joints in limestone base.	1	LS	\$ 2,000.00	5 2,000					\$ 2,00	0 \$ 2,90
3	Enclosure System	Throughout	Reseal control joints in brick.	1	LS	\$ 3,000.00	3,000					\$ 3,00	0 \$ 4,35
Finish S	ystem												
1	Finish System	Second Level	Repair gypsum soffit at main entry.	1	LS	\$ 1,500.00	5 1,500					\$ 1,50	0 \$ 2,17
2	Finish System	Second Level	Replace damaged ceiling tiles at main entry.	1	LS	\$ 1,000.00	5 1,000					\$ 1,00	0 \$ 1,45
3	Finish System	Second Level	Repair wall damage at fire doors to UC-2 - second level.	1	LS	\$ 1,000.00	5 1,000					\$ 1,00	0 \$ 1,45
Fixed Ec	quipment												
1	Fixed Equipment	General	Install cane rail under stairs.	2	EA	\$ 1,500.00	3,000					\$ 3,00	0 \$ 4,35
Tempera	emperature Controls												
1	Temperature Controls	Building	Repalce existing Siemens Desigo control system with Tridium	36718	SF			\$ 10.00	\$ 367,180			\$ 367,18	0 \$ 532,41
Power S	ystems												
			NFPA 70E requires updating arc flash studies at an interval not to exceed 5 years. The									Í	
1	Power Systems	General	existing labeling is not dated however appears to be original. It is recommended to update	1	LS					\$ 8,000.00	\$ 8,000	\$ 8,00	0 \$ 11,60
			the building-wide power systems study.									<b> </b>	
2	Power Systems	General	No signs of electrical equipment maintenance or testing since original installation in ~2007.	1	LS					\$ 20,000.00	\$ 20,000	\$ 20,00	0 \$ 29,00
Lighting	System				<u> </u>	ļ							
Lighting	System		Existing lighting is fluorescent & current controls are not fully code compliant with latest	[	-	Г Г							
1	Lighting System	General	energy codes. Recommended to replace with LED and controls as a part of the next major	36 718	SF					\$ 15.00	\$ 550 770	\$ 550.77	0 \$ 798.61
			building renovation.	00,110	0.					¢ 10.00	¢ 000,110	¢ 000,11	φ του,οι
			Multiple utility spaces contained emergency battery unit light fixtures that were broken or									Í	
2	Lighting System	Various	had battery error lights on. Immediate replacement of damaged and inoperable emergency	1	LS					\$ 5,000.00	\$ 5,000	\$ 5,00	0 \$ 7,25
			lights is recommended.									L	
						:	\$ 274,600		\$ 367,180		\$ 583,770	\$ 1,225,55	0 \$ 1,777,04



- Year Built: 2008
- Total Area: 25,444 SF
- Floors:
   2

   5 Year DMB:
   \$1,123,976

   CRV:
   \$13,103,660
- FCI: 8.58%

#### **COMMENTS**

## **Roof System**

• Duro-Last single-ply roof installed in 2009. Roof should be scheduled for replacement.

## **HVAC Systems**

• Existing rooftop HVAC unit should be scheduled for replacement.

#### **Temperature Controls**

• Building is served by both Tridium (Honeywell) and Desigo (Siemens) controls. Remove the Desigo portion and replace with Tridium.

## **Power Systems**

• Electrical equipment was upgraded in 2009 and is good condition.





BUILDING "UC 4" 200 LEVEL

No	Item/Description	Location	Notos	Otv	Linit	Jnit Architectural		Mecha	anical	Electrical		Construction	Draiget Cost
NO.	item/Description	Location	Notes	Qiy.	Unit	Unit Cost	Subtotal	Unit Cost	Subtotal	Unit Cost	Subtotal	Cost	Project Cost
Roof Sy	stem												
1	Roof System	Roof	Repaint gas piping.	1	LS	\$ 1,000.00	\$ 1,000					\$ 1,000	\$ 1,450
2	Roof System	Roof	Replace roof	12730	SF	\$ 14.00	\$ 178,220					\$ 178,220	\$ 258,419
HVAC S	ystems												
1	HVAC System	Building	Building is served by both Tridium (Honeywell) and Desigo (Siemens) controls. Remove the Desigo portion and replace with Tridium.	1	LS	\$ 3,000.00	\$ 3,000	\$ 80,000.00	\$ 80,000	\$ 3,000.00	\$ 3,000	\$ 86,000	\$ 124,700
Plumbin	ng System												
1	Plumbing System	Building	Investigate source of water leak near domestic water heater DWH-4and repair.	1	LS			\$ 500.00	\$ 500			\$ 500	\$ 725
2	Plumbing System	Building	Investigate cause of excessive natural gas order at building exterior service entrance gas pressure regulators and repair.	1	LS			\$ 500.00	\$ 500			\$ 500	\$ 725
Tempera	ature Controls												
1	Temperature Controls	Building	Building is served by both Tridium (Honeywell) and Desigo (Siemens) controls. Remove the Desigo portion and replace with Tridium.	25,444	SF			\$ 4.00	\$ 101,776			\$ 101,776	\$ 147,575
Power S	Power Systems												
1	Power Systems	General	A majority of electrical equipment was missing arc flash labels. It is recommended to provide a power system study and labeling.	1	LS					\$ 8,000.00	\$ 8,000	\$ 8,000	\$ 11,600
2	Power Systems	General	Electrical equipment had no indication of maintenance or testing since original installation in 2009. Testing / maintenance is recommended at regular intervals.	1	LS					\$ 10,000.00	\$ 10,000	\$ 10,000	\$ 14,500
3	Power Systems	Generator Yard	300kW Natural Gas Generator installed in 2015. Testing / maintenance is recommended at regular intervals. Note: The existing generator provides back up power to substation UC-4, via 800A automatic transfer switch. The generator will not be permitted to also serve future life safety loads without distribution system modifications.	1	LS					\$ 7,500.00	\$ 7,500	\$ 7,500	\$ 10,875
Lighting	J System												
1	Lighting System	General	Existing lighting is fluorescent and current controls are not fully code compliant with latest energy codes. Recommended to replace with LED and controls as a part of the next major building renovation.	25,444	SF					\$ 15.00	\$ 381,660	\$ 381,660	\$ 553,407
							\$ 182.220		\$ 182.776		\$ 410.160	\$ 775.156	\$ 1.123.976